Form CP-111 June 2011 Form must be Typed Form must be signed

## TEMPORARY ABANDONMENT WELL APPLICATION

All blanks must be complete

OPERATOR: License#				API No. 15													
Name:				Spot Description:													
Address 1:					· Sec	Twp S.	. R	E W									
Address 2:						feet from I											
City:       State:       Zip:       +				GPS Location: Lat:													
									Well Type: (check one)  Oil  Gas  OG  WSW  Other:								
									Field Contact Person Phone: ( )				SWD Permit #: ENHR Permit #:				
									,				Gas Storage Permit #: Date Shut-In:				
								Spud Date.		Date Shut-in.							
	Conductor	Surface	Pro	oduction	Intermediate	Liner	Tubing	j									
Size																	
Setting Depth																	
Amount of Cement																	
Top of Cement																	
Bottom of Cement																	
Do you have a valid Oil & C Depth and Type:	in Hole at(depth)  I. I ALT. II Depth o	Tools in Hole at	w / _	Set at:	s of cement Port	Collar: w  et											
iotai beptii.	Flug Da	ск Берш.		Flug Back Metri	ou												
Geological Date:																	
Formation Name	Formation	Formation Top Formation Base		Completion Information													
1	At:	to Feet	Perfo	ration Interval	to F	eet or Open Hole Interv	val to	Feet									
2	At:	to Feet	Perfo	ration Interval	to F	eet or Open Hole Interv	val to	Feet									
UNDER REMAITY OF RE	D IIIDV I LIEDEDV ATTE			ctronicall		ABBEATTA THE BEST	OE MA KNOWI E	EDCE									
Do NOT Write in This Space - KCC USE ONLY	Date Tested:	R	esults:		Date Plugged:	Date Repaired: Da	ate Put Back in Serv	vice:									
Review Completed by:			Comn	nents:													
TA Approved: Yes	Denied Date:																
		w															
		Mail to the App	ropriate	KCC Conserv	/ation Office:												

Note: Sade State S	KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801	Phone 620.225.8888	
State Same for the same same same same same same same sam	KCC District Office #2 / UPGS - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226	Phone 316.630.4000	
	KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720	Phone 620.432.2300	
See	KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651	Phone 785.625.0550	



## Lohrding 4A 08/26/2015 10:16:47AM





3962 ft


3962 ft

Liquid Level 1016 ft

Fluid Above Tubing
Gas Free Above Tubing







## **Comments and Recommendations**

**EXPLOSION - 650 PSI CASING** 

Colton Oldham
Weatherford Gas Lift
1900 S.E. 25th St.
Oklahoma City, Oklahoma 73129
940-389-4632
colton.oldham@weatherford.com

Conservation Division District Office No. 1 210 E. Frontview, Suite A Dodge City, KS 67801



Phone: 620-225-8888 Fax: 620-225-8885 http://kcc.ks.gov/

Sam Brownback, Governor

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner

September 08, 2015

Wanda Ledbetter SandRidge Exploration and Production LLC 123 ROBERT S. KERR AVE OKLAHOMA CITY, OK 73102-6406

Re: Temporary Abandonment API 15-033-21336-00-00 LOHRDING 4A SE/4 Sec.06-31S-19W Comanche County, Kansas

## Dear Wanda Ledbetter:

"Your temporary abandonment (TA) application for the well listed above has been approved. In accordance with K.A.R. 82-3-111 the TA status of this well will expire 09/08/2016.

- \* If you return this well to service or plug it, please notify the District Office.
- \* If you sell this well you are required to file a Transfer of Operator form, T-1.
- \* If the well will remain temporarily abandoned, you must submit a new TA application, CP-111, before 09/08/2016.

You may contact me at the number above if you have questions.

Very truly yours,

Michael Maier"