



PO Box 884, Chanute, KS 66720  
620-431-9210 or 800-467-8676

3630  
3549

INVOICE # 05557

TICKET NUMBER 49747  
LOCATION Ottawa KS  
FOREMAN Fred Maden

FIELD TICKET & TREATMENT REPORT  
CEMENT

DATE	CUSTOMER #	WELL NAME & NUMBER	SECTION	TOWNSHIP	RANGE	COUNTY
7-23-15	4807	Cross # L.O. 15	SW 22	25	17	wd
CUSTOMER			TRUCK # DRIVER TRUCK # DRIVER			
MAILING ADDRESS			712 ✓ Fred Maden			
CITY STATE ZIP CODE			495 ✓ Harbac			
340 So Laura			675 ✓ Kai Dat			
Wichita KS 67211			558 ✓ Tro Har			

JOB TYPE Longstring HOLE SIZE 5 1/8 HOLE DEPTH \_\_\_\_\_ CASING SIZE & WEIGHT 2 3/8 EUE  
 CASING DEPTH 794 DRILL PIPE \_\_\_\_\_ TUBING \_\_\_\_\_ OTHER \_\_\_\_\_  
 SLURRY WEIGHT \_\_\_\_\_ SLURRY VOL \_\_\_\_\_ WATER gal/sk \_\_\_\_\_ CEMENT LEFT IN CASING 2 1/2" Plug  
 DISPLACEMENT 4.6 BBL DISPLACEMENT PSI \_\_\_\_\_ MIX PSI \_\_\_\_\_ RATE 4.3 PM

REMARKS: Hold safety nutting. Establish circulation. Mix Pump 100# Gel Flush. Mix Pump 98 sks Por Blend II A 1/2" Gal 5" Gal seal 1" Pheno Seal/sk. Cement to surface. Flush pump + lines clean. Displace 2 1/2" Rubber plug to casing TD. Pressure to 800 PSI. Release pressure to set float valve. Shut in casing.

Jackman Well Service. Fred Maden

ACCOUNT CODE	QUANTITY or UNITS	DESCRIPTION of SERVICES or PRODUCT	UNIT PRICE	TOTAL
CE0450	1	PUMP CHARGE	495	1500.00
CE0002	40 mi	MILEAGE	495	286.00
CE0711	Minimum	Ten Miles Delivery	510	660.00
WF0853	3 hrs	80 BBL Vac Truck	675	300.00
		Sub Total		2746.00
		Less (39%)		-1070.94
				1675.06
CC5842	98 SKS	Por Blend II A Cement	1445.00	1415.10
CC5965	437# 267#	Bestonite Gal	131.10	59.83
CC6077	490#	Kal Seal	245.00	120.75
CC6079	98#	Pheno Seal	132.00	13.00
CP8176	1	2 1/2" Rubber Plug	45.00	45.00
		Sub Total		1998.98
		Less 39%		779.57
				1121.93
			7.58	SALES TAX 91.45
				ESTIMATED TOTAL 2985.84

5255

RAVIN 3737 AUTHORIZATION [Signature] TITLE \_\_\_\_\_ DATE 4894

I acknowledge that the payment terms, unless specifically amended in writing on the front of the form or in the customer's account records, at our office, and conditions of service on the back of this form are in effect for services identified on this form.