

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION 1273835

Form CDP-1 May 2010 Form must be Typed

## **APPLICATION FOR SURFACE PIT**

Submit in Duplicate

Operator Name:		License Number:		
Operator Address:				
Contact Person:			Phone Number:	
Lease Name & Well No.:		Pit Location (QQQQ):		
Depth fro	Artificial Liner? Yes No Length (feet) from ground level to deepest point:			
If the pit is lined give a brief description of the liner material, thickness and installation procedure.		liner integrity, in	ncluding any special monitoring.	
feet Depth of water wellfeet		measured well owner electric log KDWR		
Emergency, Settling and Burn Pits ONLY:		Drilling, Workover and Haul-Off Pits ONLY:		
Producing Formation:		Type of material utilized in drilling/workover:		
Number of producing wells on lease:		Number of working pits to be utilized:		
Barrels of fluid produced daily: Does the slope from the tank battery allow all spilled fluids to flow into the pit? Yes No		Abandonment procedure: Drill pits must be closed within 365 days of spud date.		
Submitted Electronically				
KCC OFFICE USE ONLY				
Date Received: Permit Num	nber:Permit			

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

Conservation Division 266 N. Main St., Ste. 220 Wichita, KS 67202-1513



Phone: 316-337-6200 Fax: 316-337-6211 http://kcc.ks.gov/

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner Sam Brownback, Governor

December 15, 2015

Matt Osborn Daystar Petroleum, Inc. 522 N. MAIN ST PO BOX 560 EUREKA, KS 67045-0560

Re: Drilling Pit Application MILLER B 4 Sec.33-15S-01W Saline County, Kansas

## Dear Matt Osborn:

District staff has inspected the above referenced location and has determined that the Workover pit shall be constructed **without slots**, the bottom shall be flat and reasonably level, and the free fluids must be removed. The fluids are to be removed from the Workover pit within 48 hours of completion of drilling operations.

## NO completion fluids or non-exempt wastes shall be placed in the Workover pit.

The fluids should be taken to an authorized disposal well. Please call the District Office at (316) 630-4000 when the fluids have been removed. Please file form CDP-5 (August 2008), Exploration and Production Waste Transfer, through KOLAR within 30 days of fluid removal.

If you have any questions or concerns please feel free to contact the District Office at (316) 630-4000.