Form CP-111 June 2011 Form must be Typed Form must be signed

All blanks must be complete

TEMPORARY ABANDONMENT WELL APPLICATION


				API No. 15-											
Name:				Spot Descri	iption:										
Address 1:					Sec	Twp	S. R	E	: W						
Address 2:						feet from	= =	=							
City: State: Zip: + Contact Person: Phone:() Contact Person Email: Contact Person Email:				GPS Location: Lat:											
										Field Contact Person:					
										Field Contact Person Phone:					
											(orage Permit #:
										Spud Date:		Date Shut-	·in:		
	Conductor	Surface	Pro							duction	Intermediate	Liner		Tubing	
Size															
Setting Depth															
Amount of Cement															
Top of Cement															
Bottom of Cement															
Do you have a valid Oil & Gas Depth and Type:	Hole at [ALT. II Depth Size:	Tools in Hole at	w / _ Inch	sacks	s of cement Por	t Collar:(depth)									
		ick Deptn:		Flug back ivietti	od:										
Geological Date:		іск Deptn:		Flug Back Meth	od:										
Geological Date: Formation Name		n Top Formation Base		Flug back Metri		ion Information									
Formation Name	Formation				Completi		Interval	to	Feet						
-	Formation	Top Formation Base	Perfo	ration Interval ₋	Completi to	on Information									
Formation Name 1	Formation At:	Top Formation Base to fo Feet to Feet	Perfo	ration Interval ₋ ration Interval -	Completi	ion Information Feet or Open Hole Feet or Open Hole									
Formation Name 1	Formation At:	Top Formation Base to to Feet to Feet Submitte	Perfo	ration Interval _ ration Interval _	Completi	ion Information Feet or Open Hole Feet or Open Hole	Interval		Feet						
Do NOT Write in This	Formation At: At: Date Tested:	Top Formation Base to to Feet to Feet Submitte	Perfo Perfo CTION COL ed Ele esults:	ration Interval	Completi toto to	Feet or Open Hole Feet or Open Hole	Interval	toto	Feet						
Do NOT Write in This Space - KCC USE ONLY	Formation At: At: Date Tested:	Top Formation Base to to Feet to Feet Submitte Re	Perfo Perfo CTION COL ed Ele esults:	ration Interval	Completi toto to	Feet or Open Hole Feet or Open Hole	Interval	toto	Feet						


Sum Sum	KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801	Phone 620.225.8888
	KCC District Office #2 / UPGS - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226	Phone 316.630.4000
	KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720	Phone 620.432.2300
	KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651	Phone 785.625.0550


(((ECHOMETER))) Ellis 3119 3-19H 12/15/2015 02:18:14PM

Liquid Level 1251 ft

Fluid Above Pump 6749 ft Equivalent Gas Free Above Pump 6749 ft







Comments and Recommendations

Explode - 700 PSI Casing

Echometer Company 5001 Ditto Lane Wichita Falls, TX 76302 (940) 767-4334 info@echometer.com Conservation Division District Office No. 1 210 E. Frontview, Suite A Dodge City, KS 67801



Phone: 620-225-8888 Fax: 620-225-8885 http://kcc.ks.gov/

Sam Brownback, Governor

Shari Feist Albrecht, Chair Jay Scott Emler, Commissioner Pat Apple, Commissioner

December 22, 2015

Wanda Ledbetter SandRidge Exploration and Production LLC 123 ROBERT S. KERR AVE OKLAHOMA CITY, OK 73102-6406

Re: Temporary Abandonment API 15-033-21691-01-00 Ellis 3119 3-19H NE/4 Sec.19-31S-19W Comanche County, Kansas

Dear Wanda Ledbetter:

"Your temporary abandonment (TA) application for the well listed above has been approved. In accordance with K.A.R. 82-3-111 the TA status of this well will expire 12/22/2016.

- * If you return this well to service or plug it, please notify the District Office.
- * If you sell this well you are required to file a Transfer of Operator form, T-1.
- * If the well will remain temporarily abandoned, you must submit a new TA application, CP-111, before 12/22/2016.

You may contact me at the number above if you have questions.

Very truly yours,

Michael Maier"