



**JOB LOG**

**SWIFT Services, Inc.**

DATE 28 OCT 15 PAGE NO. 1  
 TICKET NO. 28863

CUSTOMER Vladimir Oj WELL NO. # 1 LEASE Brent B JOB TYPE Plug to Abandon

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING	
								130sk 60/40 200ppg (4% gel)
								5 1/2 casing pull casing
								shot 2 1/2 @ 1545'
	0900							on loc TRX 114
								8 1/2 ton rack - 1290'
	0925	3 1/2	36					mix 12sk gel
		3 1/2	25			200		- fluid to surface -
		3 1/2	36			200		Switch to cement
		3 1/2	13			200		mix 60/40 (4%) @ 13.1ppg 50sk
	0955							Kickstart -
								pull to 360' / cannot get 5 1/2 to surface
								pour H <sub>2</sub> O down 5 1/2 to get pipe unstuck
		6	48			100		lobp - cement cure
								- no luck moving pipe -
	1040	3 1/2	13			100		call for logging truck for more cement
		3 1/2	22			100		MIX 50sk 60/40 200(4%) @ 13.1ppg - 1290' ago
								Displace w/ 22 bbl H <sub>2</sub> O - H <sub>2</sub> O to surface
	1340							WAIT on Perforators
	1410	3 1/2	13					Shoot @ 545' - pull pipe to 360'
		3 1/2	22					mix 60/40 (4%) @ 13.1ppg 50sk
	1425							Displace 2 1/2 bbl
	1450		6					pull to 40'
								mix 60/40 200(4%) @ 13.1ppg 20sk
								→ cement standing at surface (170sk)
								total 170sk
								wash truck
								Rack up
	1500							job complete
								Flank
								Flank at 1st & 2nd & 3rd