Form CP-111 June 2011 Form must be Typed Form must be signed

All blanks must be complete

TEMPORARY ABANDONMENT WELL APPLICATION


				API No. 15-													
Name:				Spot Description:													
Address 1:					Sec	Twp	S. R										
Address 2: State: Zip: +																	
									Gas Storage Permit #: Spud Date: Date Shut-In:								
											I	I	Spuu Date.		Date Shut-in.		
										Conductor	Surface	Pro	duction	Intermediate	Liner		Tubing
									Size								
									Setting Depth								
									Amount of Cement								
				Top of Cement													
Bottom of Cement																	
Casing Squeeze(s):		sacks of ce	ment,	(top) to	(bottom) w /	sacks of cemen	nt. Date:										
Depth and Type: Junk in Type Completion: ALT. Packer Type: Total Depth: Geological Date: Formation Name 1	Size: Size: Plug Ba Formation At:	Tools in Hole at	w / Inch Perfo Perfo	Set at: Plug Back Meth ration Interval	Completion to February Table AND Completion	collar:(depth) et In Information eet or Open Hole Inte	w /	_ sack of cement									
Depth and Type: Junk in Type Completion: ALT. Packer Type: Total Depth: Geological Date: Formation Name 1	h Hole at [(depth)	Tools in Hole at	w / Inch Perfo Perfo	Set at: Plug Back Meth ration Interval	Completion to February Table AND Completion	collar:	w /	_ sack of cement _ to Feet _ to Feet									
Depth and Type: Junk in Type Completion: ALT. Packer Type: Total Depth: Geological Date: Formation Name 1. June Benal Ty Of Benal Do NOT Write in This Space - KCC USE ONLY	Plug Ba Formation At: At: Date Tested:	Tools in Hole at	Perfo Perfo Perfo ed Ele	Set at: Plug Back Meth ration Interval ration Interval	Completion to February to Febr	collar:	ervalerval	_ sack of cement _ to Feet _ to Feet									
Depth and Type: Junk in Type Completion: ALT. Packer Type: Total Depth: Geological Date: Formation Name 1. Junice Benalty Of Bed	Plug Ba Formation At: At: Date Tested:	Tools in Hole at	Perfo Perfo Perfo ed Ele	Set at: Plug Back Meth ration Interval ration Interval	Completion to February to Febr	collar:	ervalerval	_ sack of cement _ to Feet _ to Feet									

	KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801	Phone 620.225.8888
	KCC District Office #2 / UPGS - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226	Phone 316.630.4000
	KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720	Phone 620.432.2300
Similar Street S	KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651	Phone 785.625.0550





Liquid Level 1098 ft

Fluid Above Pump	3531 ft
Equivalent Gas Free Above Pump	3173 ft



34.65 Jts





Comments and Recommendations

Static Fluid Level for TA

Joints To Liquid

Echometer Company 5001 Ditto Lane Wichita Falls, TX 76302 (940) 767-4334 info@echometer.com Conservation Division District Office No. 1 210 E. Frontview, Suite A Dodge City, KS 67801



Phone: 620-225-8888 Fax: 620-225-8885 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

March 08, 2016

Kent Roberts AGV Corp. PO Box 377 ATTICA, KS 67009-0377

Re: Temporary Abandonment API 15-007-23621-00-00 Spicer Lake 1 SE/4 Sec.02-34S-10W Barber County, Kansas

Dear Kent Roberts:

- "Your temporary abandonment (TA) application for the well listed above has been approved. In accordance with K.A.R. 82-3-111 the TA status of this well will expire 03/08/2017.
- * If you return this well to service or plug it, please notify the District Office.
- * If you sell this well you are required to file a Transfer of Operator form, T-1.
- * If the well will remain temporarily abandoned, you must submit a new TA application, CP-111, before 03/08/2017.

You may contact me at the number above if you have questions.

Very truly yours,

Michael Maier"