Form CP-111 June 2011 Form must be Typed Form must be signed

All blanks must be complete

TEMPORARY ABANDONMENT WELL APPLICATION

Name:								
			Spot Descri	ption:				
Address 2:				Sec	Twp	_ S. R		E W
						= =	=	
City: State: Z	<u> +</u>							f Section
Contact Person:			GPS Location	on: Lat:	xxxx) , Long:	(e	e.gxxx.xxxxx)	
Phone:()				NAD27 NAD83			□GI	□ KB
Contact Person Email:			Lease Name: Well #:					
Field Contact Person:			Well Type: (check one) Oil Gas OG WSW Other:					
Field Contact Person Phone: ()			SWD Permit #: ENHR Permit #:					
ieu contact reison rhone. ()			_	rage Permit #:				
			Spud Date:		Date Shut-l	ln:		
Conductor	Surface	Pro	oduction	Intermediate	Liner		Tubing	
Size								
Setting Depth								
Amount of Cement								
Top of Cement								
Bottom of Cement								
Depth and Type: Usual Junk in Hole at (depth)			sing Leaks	」res ∟_ino Depti	Tor casing leak(s).			
			sacks	of cement Port	Collar:			
Packer Type: Size:		Inch	sacks	of cement Port (Collar:(depth) et			
Packer Type: Size: Total Depth: Plug Back I		Inch	sacks	of cement Port (Collar:(depth) et			
Packer Type: Size: Total Depth: Plug Back I Geological Date:		Inch	sacks	s of cement Port (Collar:(depth) et			
Packer Type: Size: Size: Plug Back I Geological Date: Formation Name Formation To	Depth: p Formation Base	Inch	sacks Set at: Plug Back Meth	s of cement Port (Collar:	w /	sack c	f cement
Packer Type: Size:	Depth: p Formation Base	Inch	Set at: Plug Back Methors ration Interval	s of cement Port (collar: (depth) et In Information eet or Open Hole I	w /	sack c	f cement
Packer Type: Size:	Depth: p Formation Base _ to Feet	Inch	Set at: Plug Back Methor ration Interval	completion	n Information eet or Open Hole I	w /	sack c	f cement
At:	Depth: p Formation Base _ to Feet	Perfor	Set at: Plug Back Methor ration Interval -	Completion to Fe	n Information eet or Open Hole I	w /	sack c	f cement
Packer Type: Size:	Depth:	Perfor	Set at: Plug Back Methor ration Interval -	Completion to Fe	n Information eet or Open Hole I	nterval	sack c	Feet Feet
Packer Type: Size: Fotal Depth: Plug Back I Geological Date: Formation Name Formation To At: At: Do NOT Write in This Date Tested: Space - KCC USE ONLY	Depth:	Performed Electrical Control C	Set at: Plug Back Methoration Interval aration Interval ctronically	Completion to Fee	n Information eet or Open Hole I	nterval	to to	Feet Feet
Packer Type: Size: Fotal Depth: Plug Back I Geological Date: Formation Name	Depth:	Performed Electrical Colors	Set at: Plug Back Methoration Interval aration Interval ctronically	Completion to Fee	n Information eet or Open Hole I	nterval	to to	Feet Feet

KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801 Phone 620.225.8888 KCC District Office #2 / UPGS - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226 Phone 316.630.4000 KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720 Phone 620.432.2300 Phone 785.625.0550 KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651

Conservation Division District Office No. 3 1500 W. Seventh Chanute, KS 66720



Phone: 620-432-2300 Fax: 620-432-2309 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

April 18, 2016

Jim Thweatt Trimble & Maclaskey Oil LLC 110 SOUTH ST PO BOX 171 GRIDLEY, KS 66852

Re: Temporary Abandonment API 15-207-19402-00-00 F JONES 3 SE/4 Sec.24-23S-13E Woodson County, Kansas

Dear Jim Thweatt:

"Your temporary abandonment (TA) application for the well listed above has been approved. In accordance with K.A.R. 82-3-111 the TA status of this well will expire 04/18/2017.

- * If you return this well to service or plug it, please notify the District Office.
- * If you sell this well you are required to file a Transfer of Operator form, T-1.
- * If the well will remain temporarily abandoned, you must submit a new TA application, CP-111, before 04/18/2017.

You may contact me at the number above if you have questions.

Very truly yours,

Mike Heffern"