Form CP-111 June 2011 Form must be Typed Form must be signed

All blanks must be complete

TEMPORARY ABANDONMENT WELL APPLICATION

				API No. 15-				
Name:					otion:			
Address 1:						Twp S. R		
Address 2:						feet from N		
						feet from E		
City: + Contact Person:				GPS Location: Lat:, Long:				
				Datum: L	NAD27 NAD83 _	WGS84		
Phone:()						levation: Well		
Contact Person Email:						Gas OG WSW		
Field Contact Person:						GWSW ENHR Perm		
Field Contact Person Phone: (_)				age Permit #:		ιι π	
						Date Shut-In:		
	0 1 1			1 0	1.4	1	T	
Cino	Conductor	Surface	Pro	duction	Intermediate	Liner	Tubing	
Size								
Setting Depth								
Amount of Cement								
Top of Cement Bottom of Cement								
Casing Squeeze(s): (top) Oo you have a valid Oil & Gas I Depth and Type: Junk in H Type Completion: ALT. I	Lease? Yes [lole at [depth] ALT. II Depth	No Tools in Hole at	Ca	sing Leaks:	Yes No Depth	of casing leak(s):		
Total Depth:		ck Depth:		Set at:	Feet		sack of cemen	
Total Depth:	Plug Ba			Set at:	Feet		sack of cemen	
Total Depth: Geological Date: Formation Name	Plug Ba	Top Formation Base	1	Set at:	d: Feet	Information		
Geological Date: Formation Name 1	Plug Ba	Top Formation Base	Perfo	Set at:Plug Back Metho	d: Feet Completion to Fee	Information	toFeet	
Total Depth: Geological Date: Formation Name	Formation At: At:	Top Formation Base to Feet to Feet	Perfo	Set at: Plug Back Metho ration Interval _ ration Interval _	Completion to Fee	Information et or Open Hole Interval et or Open Hole Interval	toFeet	
Geological Date: Formation Name 1	Formation At: At:	Top Formation Base to Feet to Feet Submitt	Perfo	Set at: Plug Back Metho ration Interval _ ration Interval _	Completion to Fee	Information et or Open Hole Interval et or Open Hole Interval	to Feet to Feet	
Geological Date: Formation Name 1	Formation At: At: At:	Top Formation Base to Feet to Feet Submitt	Perfo	Set at: Plug Back Metho ration Interval _ ration Interval _	Completion to Fee	Information et or Open Hole Interval et or Open Hole Interval	toFeet toFeet	

Mail to the Appropriate KCC Conservation Office:

	KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801	Phone 620.225.8888
	KCC District Office #2 / UPGS - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226	Phone 316.630.4000
	KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720	Phone 620.432.2300
	KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651	Phone 785.625.0550

Conservation Division District Office No. 3 1500 W. Seventh Chanute, KS 66720



Phone: 620-432-2300 Fax: 620-432-2309 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 10, 2016

Rick House Housel, Robert E. 1030 E 3RD ST CHERRYVALE, KS 67335-1609

Re: Temporary Abandonment API 15-125-26227-00-00 DARLING 13 NW/4 Sec.03-32S-17E Montgomery County, Kansas

Dear Rick House:

- "Your temporary abandonment (TA) application for the well listed above has been approved. In accordance with K.A.R. 82-3-111 the TA status of this well will expire 10/10/2017.
- * If you return this well to service or plug it, please notify the District Office.
- * If you sell this well you are required to file a Transfer of Operator form, T-1.
- * If the well will remain temporarily abandoned, you must submit a new TA application, CP-111, before 10/10/2017.

You may contact me at the number above if you have questions.

Very truly yours,

Russell Hine"