Kansas Corporation Commission 1319018

Form CP-111 Oct 2016 Form must be Typed Form must be signed

All blanks must be complete

TEMPORARY ABANDONMENT WELL APPLICATION

			API No. 15-				
			Spot Descri	ption:			
				Sec	Twp	S. R	
					_		
State:	_ Zip: +						
Contact Person: Contact Person Email:			(e.g. xx.xxxxx) (e.gxxx.xxxxx)				
			County: Elevation: GL KB Lease Name: Well #:				
)					_	Permit #:	
,							
			Spud Date.		Date Shut-in.	. —	
Conductor	Surface	Pro	duction	Intermediate	Liner		Tubing
ase? Yes	No		sing Leaks:		n of casing leak(s):		
ALT. II Depth o	of: DV Tool: (depth) ck Depth: Top Formation Base	Inch	Set at:	od: Fee	n Information		_ sack of cement
ALT. II Depth of Size: Plug Ba	of: DV Tool:(depth)	Inch	Set at:	od: Fee	et		_ sack of cement
ALT. II Depth of Size: Plug Ba Formation At:	of: DV Tool: (depth) ck Depth: Top Formation Base	Inch	Set at:Plug Back Methor	Completion	n Information	terval	_ sack of cement
ALT. II Depth of Size: Plug Ba Formation At:	of: DV Tool: (depth) ck Depth: Feet to Feet	Perfo	Set at:Plug Back Methor	Completion to Fe	n Information eet or Open Hole Int	terval	_ sack of cement
ALT. II Depth of Size: Plug Ba Formation At:	Top Formation Base to Feet to Feet Submitte	Perfo	Set at: Plug Back Methoral _ ration Interval _ ration Interval _	Completion to Fe	n Information eet or Open Hole Int	terval terval	_ sack of cement
ALT. II Depth of Size: Size: Plug Ba Formation At: At: Date Tested:	Top Formation Base to Feet to Feet Submitte	Performed Electrical Colors and C	Set at: Plug Back Methoration Interval _ ration Interval _ ctronically	Completion to Fee	n Information eet or Open Hole Interest or O	terval terval	_ toFeet _ toFeet
ALT. II Depth of Size: Size: Plug Ba Formation At: At: Date Tested:	of: DV Tool: (depth) ck Depth: Feet to Feet to Feet Submitte	Performed Electrical Colors and C	Set at: Plug Back Methoration Interval _ ration Interval _ ctronically	Completion to Fee	n Information eet or Open Hole Interest or O	terval terval	_ toFeet _ toFeet
	State:		Conductor Surface Pro How Determined? (bottom) w / sacks of cement, Ise?	State:	State:	State: Zip: + feet from feet from	State:

	KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801	Phone 620.225.8888
	KCC District Office #2 - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226	Phone 316.337.7400
	KCC District Office #3 - 1500 SW Seventh Steet, Chanute, KS 66720	Phone 620.432.2300
	KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651	Phone 785.625.0550


ECHOMETER COMPANY PHONE-940-767-4334

JOINTS TO LIQUID	DISTANCE TO LIQUID	4 184	SBH	PROD RATE EFF, X	MAX PRODUCTION
WELL Colliver P# C	CASING PRESSURE	40 -		PRODUCTION RATE	

ECHOMETER COMPANY

UC) GENERATE	PULSE 1.10 - SS y 10 8	
10/20/2016 08:27:06 NDISY WELL	UPPER COLLARS A: 3.6 P-P 15.0 mV	

8 PHONE-940-767-4334



Conservation Division District Office No. 4 2301 E. 13th Street Hays, KS 67601-2651



Phone: 785-625-0550 Fax: 785-625-0564 http://kcc.ks.gov/

Sam Brownback, Governor

Jay Scott Emler, Chairman Shari Feist Albrecht, Commissioner Pat Apple, Commissioner

October 26, 2016

Ken Dean Murfin Drilling Co., Inc. 250 N WATER STE 300 WICHITA, KS 67202-1216

Re: Temporary Abandonment API 15-167-02480-00-03 COLLIVER A 2 SE/4 Sec.28-14S-13W Russell County, Kansas

Dear Ken Dean:

Your temporary abandonment (TA) application for the well listed above has been approved. In accordance with K.A.R. 82-3-111 the TA status of this well will expire 10/26/2017.

Your exception application expires on 10/13/2018.

- * If you return this well to service or plug it, please notify the District Office.
- * If you sell this well you are required to file a Transfer of Operator form, T-1.
- * If the well will remain temporarily abandoned, you must submit a new TA application, CP-111, before 10/26/2017.

You may contact me at the number above if you have questions.

Very truly yours,

Richard Williams