

# QUALITY WELL SERVICE, INC.

Federal Tax I.D. # 481187368

6529

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410

Fax 620-672-3663

Rich's Cell 620-727-3409

Brady's Cell 620-727-6964

Date	6-22-16	Sec.	4	Twp.	28	Range	24	County	Ford	State	Ks	On Location	12:00	Finish	3:00
Lease	Fischer														
Contractor	Duke Rig 9														
Type Job	Surface														
Hole Size	12 1/4														
Csg.	0 5/8 23#														
Tbg. Size															
Tool	Leading J4 16'														
Cement Left in Csg.	20'														
Meas Line	Displace 26.56														
<b>EQUIPMENT</b>															
Pumptrk	No.	8 mikes													
Bulktrk	No.	7 Dens													
Bulktrk	No.														
Pickup	No.	David													
<b>JOB SERVICES &amp; REMARKS</b>															
Rat Hole															
Mouse Hole															
Centralizers															
Baskets															
DM or Port Collar															
Run 10.5 kts 8 5/8 Established circulation															
with Rig. Pumped 5 bbls H 3/8 mixed															
275 sq. common cement 396cc 2 3/8 Gel															
1/4 C.F. Released Plug Displaced with															
26.56 bbls H 3/8 to 417 shot in scoops															
Cement circulated to surface															
FLOAT EQUIPMENT															
Guide Shoe															
Centralizer															
Baskets															
AFU Inserts															
Float Shoe															
Latch Down															
LMD 50															
Surface Separator															
Pumptrk Charge Surface															
Mileage 50 x 2															
														Tax	
														Discount	
														Total Charge	
Signature <i>Samuel Brown</i>															

# QUALITY WELL SERVICE, INC.

Federal Tax I.D. # 481187368

6531

Home Office 324 Simpson St., Pratt, KS 67124

Office 620-727-3410

Fax 620-672-3663

Rich's Cell 620-727-3409

Brady's Cell 620-727-6964

Date	6-29-16	Sec.	4	Twp.	28	Range	24	County	Ford	State	Ks	On Location	12:30	Finish	4:30
Lease	Fischer		Well No.		1-4		Location								
Contractor	Duke 9														
Type Job	Rotary Plug														
Hole Size	7 7/8														
Csg.	8 5/8														
Tbg. Size	Depth 437														
Tool	Depth														
Cement Left in Csg.	Depth														
Meas Line	Shoe Joint														
	Displace														
<b>EQUIPMENT</b>															
Pumptrk	No.	Mike													
Bulktrk	No.	Duro													
Bulktrk	No.														
Pickup	No.														
<b>JOB SERVICES &amp; REMARKS</b>															
Rat Hole	305x 60/40 4 1/2 Gal														
Mouse Hole	205x 60/40 4 1/2 Gal														
Centralizers															
Baskets															
DM or Port Collar															
1st Drill pipe @ 1570 Load hole with mud. pumped water spacer.															
pumped 50ss 60/40 4 1/2 Gal Displaced with 18 HLLs H2O															
<b>FLOAT EQUIPMENT</b>															
2nd Drill pipe @ 840' Load hole with mud.															
pumped water spacer. pumped 80ss 60/40 4 1/2 Gal Displaced with Ehlls H2O															
3rd Drill pipe @ 470' Load hole with mud															
pumped 50ss 60/40 4 1/2 Gal displaced with 4 hlls H2O.															
4th Drill pipe @ 60' pumped 20ss 60/40 4 1/2 gal to surface.															
Signature <i>Simpson</i>															
															Tax
															Discount
															Total Charge