



**BASIC**<sup>SM</sup>  
ENERGY SERVICES  
PRESSURE PUMPING & WIRELINE

10244 NE Hwy. 61  
P.O. Box 8613  
Pratt, Kansas 67124  
Phone 620-672-1201

*Trml = 21*

**FIELD SERVICE TICKET**  
1718 15494 A

DATE \_\_\_\_\_ TICKET NO. \_\_\_\_\_

DATE OF JOB <i>11/1/2017</i> DISTRICT <i>Libersin, KS</i>		NEW WELL <input type="checkbox"/> OLD WELL <input checked="" type="checkbox"/> PROD <input type="checkbox"/> INJ <input type="checkbox"/> WDW <input type="checkbox"/> CUSTOMER ORDER NO.:							
CUSTOMER <i>Steibsc</i>		LEASE <i>Zixie</i> WELL NO. <i>1-24</i>							
ADDRESS		COUNTY <i>Finney</i> STATE <i>KS</i>							
CITY STATE		SERVICE CREW <i>Dustin, Ansel, Scott, GSO</i>							
AUTHORIZED BY		JOB TYPE: <i>241/PTA</i>							
EQUIPMENT#	HRS	EQUIPMENT#	HRS	EQUIPMENT#	HRS	TRUCK CALLED	DATE	AM	TIME
<i>19919</i>	<i>1</i>						<i>11/1</i>	PM	<i>2:30</i>
<i>19808</i>	<i>1/2</i>						<i>11/1</i>	PM	<i>2:30</i>
							<i>11/1</i>	AM	<i>3:00</i>
							<i>11/1</i>	PM	<i>4:00</i>
							<i>11/1</i>	AM	<i>4:30</i>
						MILES FROM STATION TO WELL	<i>90</i>		

CONTRACT CONDITIONS: (This contract must be signed before the job is commenced or merchandise is delivered).

The undersigned is authorized to execute this contract as an agent of the customer. As such, the undersigned agrees and acknowledges that this contract for services, materials, products, and/or supplies includes all of and only those terms and conditions appearing on the front and back of this document. No additional or substitute terms and/or conditions shall become a part of this contract without the written consent of an officer of Basic Energy Services LP.

SIGNED: \_\_\_\_\_  
(WELL OWNER, OPERATOR, CONTRACTOR OR AGENT)

ITEM/PRICE REF. NO.	MATERIAL, EQUIPMENT AND SERVICES USED	UNIT	QUANTITY	UNIT PRICE	\$ AMOUNT
<i>CL103</i>	<i>60/40 P02 (L)</i>	<i>SK</i>	<i>110</i>		<i>1320 00</i>
<i>CC200</i>	<i>Cement + Gel (L)</i>	<i>Lb</i>	<i>190</i>		<i>47 50</i>
<i>C2410</i>	<i>Cotton Seed Husks (L)</i>	<i>Lb</i>	<i>50</i>		<i>17 50</i>
<i>E101</i>	<i>Hesvy Equipment + Mileage</i>	<i>M.</i>	<i>50</i>		<i>375 00</i>
<i>CF240</i>	<i>Blending &amp; mixing Service Charge</i>	<i>SK</i>	<i>110</i>		<i>154 00</i>
<i>E113</i>	<i>Pickups + 800 Bulk Delivery charges, per ton mile</i>	<i>ton</i>	<i>119</i>		<i>290 00</i>
<i>CF202</i>	<i>Depth Charge; 1,001 - 2,000'</i>	<i>4hrs</i>	<i>1</i>		<i>1500 00</i>
<i>F100</i>	<i>unit + mileage Charge - pickups, 3 hrs, 10 hrs, 2 hrs</i>	<i>M.</i>	<i>25</i>		<i>112 50</i>
<i>S003</i>	<i>Service supervisor, 1 hr 8 hrs on loc</i>	<i>Es</i>	<i>1</i>		<i>175 00</i>
<i>T105</i>	<i>Cement DSGs Acquisition Monitor</i>	<i>Es</i>	<i>1</i>		<i>550 00</i>
					SUB TOTAL <i>4,539 00</i>

CHEMICAL / ACID DATA:			

SERVICE & EQUIPMENT	%TAX ON \$		
MATERIALS	%TAX ON \$		
DISCOUNT TOTAL		<i>2501 61</i>	

SERVICE REPRESENTATIVE *Don Evans*

THE ABOVE MATERIAL AND SERVICE ORDERED BY CUSTOMER AND RECEIVED BY: *[Signature]*

(WELL OWNER OPERATOR CONTRACTOR OR AGENT)

FIELD SERVICE ORDER NO.



Customer <i>Stelber</i>	Lease No.	Date <i>11/1/2017</i>	
Lease <i>Zippie</i>	Well # <i>1-24</i>		
Field Order # <i>15494</i>	Station <i>Pratt L. Hwy 1, Jr</i>	Casing	Depth
Type Job <i>241/PTA</i>	Formation	County <i>Finney</i>	State <i>Ks</i>
		Legal Description <i>24-215-336</i>	

PIPE DATA		PERFORATING DATA		FLUID USED	TREATMENT RESUME		
Casing Size	Tubing Size	Shots/Ft		Acid	RATE	PRESS	ISIP
<i>4 1/2</i>							
Depth <i>1150</i>	Depth	From	To	Pre Pad	Max		5 Min.
Volume	Volume	From	To	Pad	Min		10 Min.
Max Press	Max Press	From	To	Frac	Avg		15 Min.
Well Connection	Annulus Vol.	From	To		HHP Used		Annulus Pressure
Plug Depth	Packer Depth	From	To	Flush <i>Freshwater</i>	Gas Volume		Total Load

Customer Representative <i>Tyson</i>	Station Manager <i>Tyler Davis</i>	Treater <i>Darin Franklin</i>
Service Units <i>92911 38117 19919 70897 19808</i>		
Driver Names <i>Darin Darin Darin SSN 1990 SSN 1990</i>		

Time	Casing Pressure	Tubing Pressure	Bbbs. Pumped	Rate	Service Log
					<i>1105K 60/40 P02 4 1/2 GRI</i>
					<i>13.5 pps, 1.50 v. 12, 2.50 w. 910</i>
					<i>Perf - 1100</i>
<i>500</i>			<i>4</i>	<i>4/4</i>	<i>Test Plug</i>
<i>1,000</i>			<i>3</i>	<i>2</i>	<i>R910</i>
<i>1,000</i>			<i>13</i>	<i>2.5</i>	<i>mix 50SK 60/40 P02</i>
<i>1,000</i>			<i>12 1/2</i>	<i>2.5</i>	<i>Displace 12 1/2 bbs w. 910</i>
					<del><i>Job complete / Darin down</i></del>
					<del><i>Therac build</i></del>
					<i>Perf 385</i>
					<i>Log &amp; hole</i>
<i>0</i>			<i>16</i>	<i>2.5</i>	<i>mix 60 SK 60/40 P02</i>
					<i>Shut down</i>
					<i>Cement circulate</i>
					<i>Job complete / Darin down</i>
					<i>Therac build</i>