

DANIELS READY MIX

2016 COUNTRY CLUB ROAD

P.O. BOX 842 • WINFIELD, KANSAS 67156

PHONE: (620) 221-9060 • FAX: (620) 221-7525

No.

039106

PLANT	LOAD TIME	DATE	ACCOUNT	GYLINDERS TAKEN	TRUCK	DRIVER	CONTROL NUMBER
			BUTLER BRO				

CUSTOMER NAME
BUTLER BROTHERS
2004S JEON CT
WINFIELD

DELIVERY ADDRESS

PURCHASE ORDER	SALES ORDER	TAX	CREDIT	ORDERED	DELIVERED	UNIT PRICE	AMOUNT
				12,000	5,000	90.00	500.00

LOAD QTY.	PRODUCT	DESCRIPTION
6,000	4-7 10SK OIL	10SK GOVERNMENT / 400ASH

Borden Unit 9-2 WFLH

LEAVE PLANT	ARRIVE JOB SITE	START DISCHARGE	FINISH DISCHARGE	ARRIVE PLANT

BY ACCEPTANCE OF THIS LOAD, THE PROPERTY OWNER, CONTRACTOR, SUB CONTRACTOR AND FINISHER AGREE TO THE FOLLOWING STATEMENTS (1-6).


- Customer assumes responsibility for a suitable roadway from the public highway to point of delivery and is liable for any damages to or by Seller's truck after leaving the highway.
- WARNING: CAUTION: Freshly mixed cement, mortar, concrete or grout may cause skin injury. Avoid contact with skin where possible and wash exposed areas promptly with water. If any cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention. KEEP OUT OF REACH OF CHILDREN.
- This concrete contains correct water content for strength of mix indicated. We do not assume responsibility for strength test when water is added after truck leaves our plant.
- This concrete conforms to ASTM #94. No change is herewith authorized.
- We do not guarantee the finished results obtained from this load of concrete. Too many factors not under our control can affect the ultimate results.
- KANSAS LIEN LAW INFORMATION (from K.S.A. 60-1103a(b)(1))
Notice to Owners: If you pay the contractor for work or equipment, material, or supplies delivered without having received from the contractor a waiver of lien by all subcontractors, or other evidence of payment to all contractors a lien may be filed against your property by a subcontractor. You may request from the contractor a list of all subcontractors. If you received notice of filing a lien statement by a subcontractor, you may withhold from the contractor the amount claimed in the subcontractor's statement pending resolution of the dispute.

SUB TOTAL
TAX
TOTAL
PREVIOUS TOTAL
GRAND TOTAL

500.00
39.00
539.00
0.00

TERMS: Invoices due on 10th of the month. A FINANCE CHARGE of 2% per Month, which is an Annual Rate of 24% will be charged on all accounts not paid by the following billing date.
*Customer agrees to pay reasonable attorney and/or collection fees should it become necessary to refer this bill for collection.

Rec'd by Dana Hall Gallons Water Added at Customers Request



DANIELS READY MIX

2016 COUNTRY CLUB ROAD

P.O. BOX 842 - WINFIELD, KANSAS 67156

PHONE: (620) 221-9060 - FAX: (620) 221-7525

No.

039107

PLANT	LOAD TIME	DATE	ACCOUNT	CYLINDERS TAKEN	TRUCK	DRIVER	CONTROL NUMBER
WINFIELD	7:30	10/26/11	11111111	10	10	111111	111111
CUSTOMER NAME MRS. JENN CL...							
DELIVERY ADDRESS WINFIELD							
PURCHASE ORDER		SALES ORDER		TAX		CREDIT	
LOAD QTY.		PRODUCT		DESCRIPTION		ORDERED	
1.000		4056 OIL		4056 OIL		12.000	
						UNIT PRICE	
						05.000	
						AMOUNT	
						500.000	

BURBEN UNIT 9-2 WFL

LEAVE PLANT	ARRIVE JOB SITE	START DISCHARGE	FINISH DISCHARGE	ARRIVE PLANT

BY ACCEPTANCE OF THIS LOAD, THE PROPERTY OWNER, CONTRACTOR, SUB CONTRACTOR AND FINISHER AGREE TO THE FOLLOWING STATEMENTS (1-6).

- Customer assumes responsibility for a suitable roadway from the public highway to point of delivery and is liable for any damages to or by Seller's truck after leaving the highway.
- WARNING: CAUTION:** Freshly mixed cement, mortar, concrete or grout may cause skin injury. Avoid contact with skin where possible and wash exposed areas promptly with water. If any cement mixtures get into eyes, rinse immediately and repeatedly with water and get prompt medical attention. **KEEP OUT OF REACH OF CHILDREN.**
- This concrete contains correct water content for strength of mix indicated. We do not assume responsibility for strength test when water is added after truck leaves our plant.
- This concrete conforms to ASTM # 94. No change is herewith authorized.
- We do not guarantee the finished results obtained from this load of concrete. Too many factors not under our control can affect the ultimate results.
- KANSAS LIEN LAW INFORMATION**
(from K.S.A. 60-1103a(b)(1))
Notice to Owners: If you pay the contractor for work or equipment, material, or supplies delivered without having received from the contractor a waiver of lien by all subcontractors, or other evidence of payment to all subcontractors, a lien may be filed against your property by a subcontractor. You may request from the contractor a list of all subcontractors. If you received notice of filing a lien statement by a subcontractor, you may withhold from the contractor the amount claimed in the subcontractor's statement pending resolution of the dispute.

SUB TOTAL
TAX
TOTAL
PREVIOUS TOTAL
GRAND TOTAL

TERMS: Invoices due on 10th of the month. A FINANCE CHARGE of 2% per Month, which is an Annual Rate of 24% will be charged on all accounts not paid by the following billing date.
*Customer agrees to pay reasonable attorney and/or collection fees should it become necessary to refer this bill for collection.

Rec'd by *[Signature]* Gallons Water Added at Customers Request