



PRESSURE PUMPING LLC
 PO Box 884, Chanute, KS 66720
 620-431-9210 or 800-467-8676

11632
 11520

TICKET NUMBER 55450
 LOCATION Ottawa, KS
 FOREMAN Casey Kennedy

FIELD TICKET & TREATMENT REPORT
 CEMENT

Invoice # 814171

DATE	CUSTOMER #	WELL NAME & NUMBER	SECTION	TOWNSHIP	RANGE	COUNTY
9/20/18	4015	Wingert # P-13	NW 9	17	22	MI
CUSTOMER JTC Oil Inc.						
MAILING ADDRESS 35790 Plum Creek						
CITY Osawatomie		STATE KS	ZIP CODE 66064			
JOB TYPE <u>long string</u>		HOLE SIZE <u>5 7/8"</u>	HOLE DEPTH <u>740'</u>	CASING SIZE & WEIGHT <u>2 7/8" EVE</u>		
CASING DEPTH <u>718'</u>		DRILL PIPE	TUBING	OTHER		
SLURRY WEIGHT		SLURRY VOL	WATER gal/sk	CEMENT LEFT in CASING		
DISPLACEMENT <u>4.16 bbls</u>		DISPLACEMENT PSI	MIX PSI	RATE <u>4 bpm</u>		

TRUCK #	DRIVER	TRUCK #	DRIVER
729 ✓	Car Ken	✓	Safety Meeting
495 ✓	Har Bec	✓	
558 ✓	Kei Car	✓	
675 ✓	Kei Det	✓	

REMARKS: held safety meeting, established circulation, mixed & pumped 200 # Gel followed by 5 bbls fresh water, mixed & pumped 59 sks Thixoblend II cement w/ 1/2 # Flosal per sk, cement to surface, flushed pump clean, pumped 2 1/2" rubber plug to casing TD w/ 4.16 bbls fresh water, pressured to 800 PSI, released pressure to set float valve.

[Handwritten signature]

ACCOUNT CODE	QUANTITY or UNITS	DESCRIPTION of SERVICES or PRODUCT	UNIT PRICE	TOTAL
CE0450 ✓	1	PUMP CHARGE	1500.00 ✓	
CE0002 ✓	on lease	MILEAGE		
CE0711 ✓	1/3 min	ten mileage	220.00 ✓	
WE0553 ✓	1 hr	80 vac	100.00 ✓	
		trucks	1820.00	
		-45%	819.00	
		subtotal		1001.00
CC5861 ✓	59 sks	Thixoblend II cement	1593.00 ✓	
CC5965 ✓	200 #	Gel	60.00 ✓	
CC6075 ✓	30 #	Flosal	60.00 ✓	
CP8176 ✓	1	2 1/2" rubber plug	45.00 ✓	
		materials	1758.00	
		-45%	791.10	
		subtotal		966.90
SCANNED				
		8%	SALES TAX	77.35 ✓
			ESTIMATED TOTAL	2045.25 ✓
				(3718.64)

Ravin 3737 AUTHORIZATION [Signature] TITLE _____ DATE _____

I acknowledge that the payment terms, unless specifically amended in writing on the front of the form or in the customer's account records, at our office, and conditions of service on the back of this form are in effect for services identified on this form