



PRESSURE PUMPING LLC
 PO Box 884, Chanute, KS 66720
 620-431-9210 or 800-467-8676

11703
 11886

TICKET NUMBER 55463
 LOCATION Ottawa, Ks
 FOREMAN Carey Kennedy

FIELD TICKET & TREATMENT REPORT
 CEMENT

Invoice #814234

DATE	CUSTOMER #	WELL NAME & NUMBER	SECTION	TOWNSHIP	RANGE	COUNTY
9/20/18	4015	Wingert # I-7	NW9	17	22	Mi
CUSTOMER			TRUCK #			
JTC Oil Inc.			729	Cas Ken	467	Safety
MAILING ADDRESS			548	Har Bec	675	Kei Det
35790 Plum Creek Rd			DRIVER			
CITY			TRUCK #			
Osawatomie			DRIVER			
STATE			TRUCK #			
KS			DRIVER			
ZIP CODE			TRUCK #			
66064			DRIVER			

JOB TYPE long string HOLE SIZE 5 7/8" HOLE DEPTH 740' CASING SIZE & WEIGHT 2 7/8" EVE
 CASING DEPTH 720' DRILL PIPE _____ TUBING _____ OTHER _____
 SLURRY WEIGHT _____ SLURRY VOL _____ WATER gal/sk _____ CEMENT LEFT in CASING _____
 DISPLACEMENT 4.17 bbls DISPLACEMENT PSI _____ MIX PSI _____ RATE 4 bpm

REMARKS: held safety meeting, established circulation, mixed & pumped 200# Gel followed by 5 bbls fresh water, mixed & pumped 62 stks Thixoblend II cement w/ 1# Phenoseal per sk, cement 1 to surface, flushed pump clean, pumped 2 1/2" rubber plug to casing TD w/ 4.17 bbls fresh water, pressured to 800 PSI, well held pressure for 30 min MIT, released pressure to set float valve.

Handwritten signature/initials

ACCOUNT CODE	QUANTITY or UNITS	DESCRIPTION of SERVICES or PRODUCT	UNIT PRICE	TOTAL
CE0450	1	PUMP CHARGE	1500.00	
CE0002	25 mi	MILEAGE	178.75	
CE0711	1/4 min	ten mileage	165.00	
WE0853	1 hr	80 Vac	100.00	
		trucks	1943.75	
		-45%	874.69	
		Subtotal		1069.06
CC5866	62 stks	Thixoblend II cement	1674.00	
CC5965	200 #	Gel	60.00	
CC6079	62 #	Phenoseal	83.70	
CP8176	1	2 1/2" rubber plug	45.00	
		materials	1862.70	
		-45%	838.22	
		Subtotal		1024.48
		8%		81.96
		SALES TAX		81.96
		ESTIMATED TOTAL		2175.50
				(395.47)

SCANNED

AUTHORIZATION AS 9/20

TITLE _____ DATE _____

I acknowledge that the payment terms, unless specifically amended in writing on the front of the form or in the customer's account records, at our office, and conditions of service on the back of this form are in effect for services identified on this form.