

QUALITY WELL SERVICE, INC.

6993

Federal Tax I.D. # 481187368

Home Office 30060 N. Hwy 281, Pratt, KS 67124

Mailing Address P.O. Box 468

Office 620-727-3410

Fax 620-672-3663

Rich's Cell 620-727-3409

Brady's Cell 620-727-6964

*JWS
2/19/03*

Phugwell

Date <i>11-29-18</i>	Sec. <i>34</i>	Twp. <i>32</i>	Range <i>12</i>	County <i>Barber</i>	State <i>Ks</i>	On Location	Finish
Lease <i>Dillman Ash</i>		Well No. <i>5</i>		Location			
Contractor <i>Alliance</i>				Owner			
Type Job <i>PTA</i>				To Quality Well Service, Inc. You are hereby requested to rent cementing equipment and furnish cementer and helper to assist owner or contractor to do work as listed.			
Hole Size		T.D.		Charge To <i>Griffin</i>			
Csg.		Depth		Street			
Tbg. Size <i>27/8</i>		Depth		City			
Tool		Depth		State			
Cement Left in Csg.		Shoe Joint		The above was done to satisfaction and supervision of owner agent or contractor.			
Meas Line		Displace		Cement Amount Ordered <i>1255x 60/40 4% Gel</i>			
EQUIPMENT							
Pumptrk <i>6</i>	No.			<i>105x 60el on side</i>			
Bulktrk <i>10</i>	No.			Common <i>75</i>			
Bulktrk	No.			Poz. Mix <i>50</i>			
Pickup	No.			Gel. <i>14</i>			
				Calcium			
JOB SERVICES & REMARKS							
Rat Hole				Hulls			
Mouse Hole				Salt			
Centralizers				Flowseal			
Baskets				Kol-Seal			
D/V or Port Collar				Mud CLR 48			
<i>1st Pumped 105x 60el 505x 60/40</i>				CFL-117 or CD110 CAF 38			
<i>4% Gel @ 610'</i>				Sand			
<i>2nd Pumped 505x 60/40 4% gel @ 318'</i>				Handling <i>139</i>			
				Mileage <i>20</i>			
<i>3rd Pumped 25.5x 60/40 11% gel @ 62' to surface</i>				FLOAT EQUIPMENT			
				Guide Shoe			
				Centralizer			
				Baskets			
				AFU Inserts			
				Float Shoe			
				Latch Down			
				<i>LMI 20</i>			
				<i>Service supervisor</i>			
				Pumptrk Charge <i>PTA</i>			
				Mileage <i>40</i>			
						Tax	
						Discount	
						Total Charge	
X Signature <i>[Signature]</i>							