KOLAR Document ID: 1483631

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

Kansas Corporation Commission Oil & Gas Conservation Division

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
March 2009
Type or Print on this Form
Form must be Signed
All blanks must be Filled

OPERATOR: License #:			A	PI No. 1	15			
			Si	oot Des	scription:			
Address 1:					•	vp S. R East West		
Address 2:					Feet from			
City:	State:	Zip: +	_		Feet from	East / West Line of Section		
Contact Person:			Fo	Footages Calculated from Nearest Outside Section Corner:				
Phone: ()					NE NW	SE SW		
Type of Well: (Check one) C Water Supply Well C ENHR Permit #: Is ACO-1 filed? Yes Producing Formation(s): List A Depth to Depth to	Other: Gas Sto No If not, is well If needed attach another Top: Botto Top: Botto	rage Permit #: Yes	Le Le Le Le Le Le Le Le	ease Na ate Wel he plug /:	ame: Il Completed: Iging proposal was appro	well #: (Date) (KCC District Agent's Name)		
Show depth and thickness of a	all water, oil and gas forma	ations.	I					
Oil, Gas or Water	Records		Casing Reco	Record (Surface, Conductor & Production)				
Formation	Content	Casing	Size		Setting Depth	Pulled Out		
Describe in detail the manner cement or other plugs were us		_	•			ds used in introducing it into the hole. If		
Plugging Contractor License #	::		Name:					
Address 1:			Address 2: _					
City:			St	ate:		Zip:+		
Phone: ()								
Name of Party Responsible for	r Plugging Fees:							
State of	County, _		,	SS.				
	(Drint Nove)			Er	mployee of Operator or	Operator on above-described well,		

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

CUSTOMER DKOPIETING		WELL NO.			LEASEDTINGER		Phy to thousan TICKET NO. 32814	
CHART	TIME	RATE	VOLUME		MPS	PRESSU	IRE (PSI)	DESCRIPTION OF OPERATION AND MATERIALS
NO.	1	(BPM)	(BBL) (GAL)	T	С	TUBING	CASING	
								50 sk 60/40 poznik (4% gel)
								28 52. + thing to 4525 aprile 453
								,
	1300							on be toke 114
								fleid pprox 1300'
								0
	1325	32				eh		M/x 60/40 poznix (40/ge) @ 13.1 pg
	1223	2				4		With cold sound cold et sites
		21	.7			~		w/ 250 hulls 5050
	-	32	17			9		
			*01			-1		
		38	16			9		Displace w H20 - cerest to botto
								- 27 on vacuum - no circ to pit -
	1338							wash thick
								pull today
								Back up
	1405							jub coplete-fortoday-
	100							Hearts Blain Alint & 15800
	0850							
	0000							Ded @ 1650'
		31	15				75	1 1 1 1 1
		02	10				350	Dup into put down 52"
								dails to vacuum
								Mix 60/40 pozux (490gel) @ 13.10
		3/2	le				350	255k Nea!
		32	6				9	253kw/ 23k holls
								255kw/ 2.5k holls
			27					Displace to perfis
4			1					slight viewn
	0930							Run into pay @ 700'
	1020							pup 420 - catch gressue 8661
	1000							-85 Alica Carent Cooke Soll
		35					200	M (18/10 - (What 1 10 12)
		-	14				200	- Cife Alust to Pit -
			46					
			-16					contitosupas fun 8 %

DK 0 zeratyg			WELL NO.	- He	LEASE SPATIGET	Plu; to Abandon	20 LOV 19 2 TICKET NO. 32814
ART	TIME	RATE	VOLUME	PUMPS	PRESSURE (PSI)	DESCRIPTION OF OPERAT	
0.		(BPM)	(BBL) (GAL)	T C	TUBING CASING		
			2) /			- Comet to say	ace
-			46			(175	Sters
						7	
						Drop ox 5xc	2 rock
						(2250))
						wait 15	
						Drop second of	find oak
						(SANC)	
			6			MIX 60/40 x02/490)	25sk @13.1
						down 52"	
						Drap officel for	ek_
						(5k. 1 25	sec)
						- will cheek plaid leve	el tomorrow—
	1120					woh truck	
						Rotck 40	
	1150					- job complete	2 -
	1100					46	
						Bloom, Fint,	t 15AAC
			-				
	-						
		-					
				4			
						•	
-							
_							