
Form CP-111
July 2017
Form must be Typed
Form must be signed
All blanks must be complete

## TEMPORARY ABANDONMENT WELL APPLICATION

				API No. 15-					
Name:					ription:				
Address 1:					Sec	Twp	_ S. R		
Address 2:									
City:	State:	_ Zip: +			ion: Lat:				
Contact Person:				Datum:	ion: Lat:	xxx) , Long	(e	.gxxx.xxxxx)	
Phone:( )					E			GLKB	
Contact Person Email:					ne:				
Field Contact Person:				Well Type: (check one)  Oil  Gas  OG  WSW  Other:					
Field Contact Person Phone: (	)				ermit #:		Permit #:		
				_	orage Permit #:		n:		
0:	Conductor	Surface	Pro	oduction	Intermediate	Liner		Tubing	
Size									
Setting Depth  Amount of Cement									
Top of Cement									
Bottom of Cement									
Casing Fluid Level from Surfact Casing Squeeze(s):	to w /	/ sacks of ce							
Depth and Type:  Junk in F Type Completion:  ALT. I Packer Type:   Total Depth:    Geological Date: Formation Name  1.   2.    LINDER BENALTY OF REP II	ALT. II Depth of Size:  Plug Ba  Formation  At:  At:	Tools in Hole at	w /w / Inch	Set at:  Plug Back Meth ration Interval	Completion to Fee	collar:(depth)  t  Information  eet or Open Hole Indepted Open Indepted In	w /	sack of cemen	
Type Completion: ALT. I  Packer Type:  Total Depth:  Geological Date:  Formation Name  1  2	ALT. II Depth of Size:  Plug Ba  Formation  At:  At:	Tools in Hole at	w /w / Inch	Set at:  Plug Back Meth ration Interval	Completion to Fee	collar:(depth)  t  Information  eet or Open Hole Indepted Open Indepted In	nterval	sack of cemen	
Type Completion: ALT. I Packer Type: Total Depth:  Geological Date: Formation Name  1  2  Do NOT Write in This Space - KCC USE ONLY	ALT. II Depth of Size: Plug Ba  Formation At: At:	Tools in Hole at	w /w /w /	Set at:  Plug Back Meth ration Interval	Completion to Fee	t (depth)  In Information  Seet or Open Hole In  Seet or Open Hole In	nterval	to Feet to Feet	
Type Completion: ALT. I Packer Type: Total Depth:  Geological Date: Formation Name  1  2  Do NOT Write in This	ALT. II Depth of Size: Plug Ba  Formation At: At:	Tools in Hole at	w /w /w /	Set at:  Plug Back Meth  ration Interval ration Interval ctronical	Completion to Fee	t (depth)  In Information  Seet or Open Hole In  Seet or Open Hole In	nterval	to Feet to Feet	

	KCC District Office #1 - 210 E. Frontview, Suite A, Dodge City, KS 67801	Phone 620.682.7933
	KCC District Office #2 - 3450 N. Rock Road, Building 600, Suite 601, Wichita, KS 67226	Phone 316.337.7400
	KCC District Office #3 - 137 E. 21st St., Chanute, KS 66720	Phone 620.902.6450
	KCC District Office #4 - 2301 E. 13th Street, Hays, KS 67601-2651	Phone 785.261.6250

## Barton Sundance 2



Conservation Division District Office No. 2 3450 N. Rock Road Building 600, Suite 601 Wichita, KS 67226



Phone: 316-337-7400 Fax: 316-630-4005 http://kcc.ks.gov/

Laura Kelly, Governor

Andrew J. French, Chairperson Dwight D. Keen, Commissioner Susan K. Duffy, Commissioner

August 23, 2021

Joe Driskill Endeavor Energy Resources, LP 110 N MARIENFELD, STE 200 MIDLAND, TX 79701-4412

Re: Temporary Abandonment API 15-191-22353-00-00 BARTON SUNDANCE 2 SE/4 Sec.01-35S-02E Sumner County, Kansas

## Dear Joe Driskill:

Your application for Temporary Abandonment (TA) for the above-listed well is denied for the following reasons(s):

Shut in date does not coincide with the last reported production.

Pursuant to K.A.R. 82-3-111, the well must be plugged, or returned to service, or obtain temporary abandonment status by 09/22/2021.

This deadline does NOT override any compliance deadline given to you in any Commission Order.

You may contact me if you have any questions.

Sincerely, Dan Fox KCC DISTRICT 2