

Rush

KANSAS

SECTION 17 TOWNSHIP 19S RANGE 20W

WELL NO. #1 Schneider

COMPANY Artnell

		NORTH		NW		NE		SE			
										9	
WEST								0			EAST
		SOUTH									

CO. ~~Rush~~ ELEV. 2271
SEC. 17 TWP. 19 RGE. 20W
COMPANY Artnell NO. 1

ABANDONED
OCT 30 '57

FARM Schneider

LOC. NW NE SE

Tops	
Anhy	1500
H6	3794
L	3837
ce	4315
ce sd	4317
M	4391
TD	4421

GEOL. _____
CONTR. Leben Drlg. tools
POOL Webs SW
SPUD 9-27-57
8" @ 523 w/325, Drlg 1670
OCT 9 '57 D 3960
Crd 4310-27
rec full
DST 4314-27
60" 125' OCM

FP 5-55 BHP 1010-715

5L 4420/100 OCT 23 '57 CO. 28/4395

4402 B 1070 ph NW 3 hrs

1/2 \$40 OCT 30 '57 \$5BN + trail

3 hr PB 0355 121

4316-19 \$ 1590 ph NW

4 hrs 1/2 \$.84 B fld ph

3390 oil \$.42 B fld ph

7590 oil \$ 1.10 hrs FU

2L2 B 0^{10 hrs} frac

20/4316-21 frac 5x5

\$40 1B0ph

T & A

CO.
LSE.
NO.
SEC.
TWP.
RGE.