

State

Kansas

County

Harper

Company

Huber Oil Corp.

Well No.

1

Farm

Catcher

Survey

Block No.

Sec.

11c

Twp.

34ⁿ

Range

7^w


Co-Ord.

Elev.

1405 KB

No. Se. Ne

Rig # 1395 GR



100% - J.M. Huber Corp.
not nec to call

NOTE: Show Sketch of Lease and Well Location in Above Space

1650 Ft. from N. Line

Ft. from S. Line

Ft. from W. Line

330

Ft. from E. Line

Date	Depth	
		Spd 12-27-55
12-23		m.o.r.g
12-27		R.U.R.G
12-28		8 5/8" @ 317' w/ 250' of cement, abge 5' cc. P.D. 30m 12-28 Thoc
12-29	560	Drig. S. U. A. 3:15 am
12-30	1723	Drig. (3/4" @ 1610)
12-31	2230	Drig. (1/2" @ 1855)
1-1-56	2765	Drig.
1-2	3269	Drig. (Trued up 3010)

716466

Date	Depth	
1-3	3584	Dry ($1/2^\circ$ @ 3458)
1-4	3695	Dry (Having lost circ table)
1-5	3853	Making det 3843-53
1-6	4017	Dry ($3/4^\circ$ @ 3853)
1-7	4084	Kansas City
	4177	Dry (1° @ 4174)
1-8	4288	"
1-9	4442	"
1-10	4557	Making trip ($3/4^\circ$ @ 4462)
1-11	4705	Miss Chat
	4715	On bank for bit trip.
1-12	4812	Making trip ($1 1/4^\circ$ @ 4789)
1-13	4935	Dry ($1 1/2^\circ$ @ 4812) Down 3 hrs last night because of lost circ. Still losing some mud
1-14	4988	Making trip ($1 1/2^\circ$ @ 4812)
	5151	Viscal (-3746)
1-16	5169	Dry. (Hole has been) raising View now up to 106)
	5175	Simpson (-3770)
1-17	5205	Dry (Hole still raising)
1-18	5243	Coming off bottom for trip
1-19	5265	Last drive collars in hole. Have them out ready to drive ahead this morning.
1-20	5329	Dry

State Kansas County Harper

Company Huber Oil Corp Well No. 1

Farm Cocher

Survey _____

Block No. _____ Sec. 16 Twp. 34 S Range 7 W

Co-Ord. _____ Elev. _____

Ne Se Ne

Page 2

NOTE: Show Sketch of Lease and Well Location in Above Space

Ft. from N. Line _____ Ft. from S. Line _____

Ft. from W. Line _____ Ft. from E. Line _____

Date	Depth	
	5393	Arbuckle (-3788)
1-21	5447	Drly. To diller to 5451 and log.
1-23	5451	R.J.D. Ran log (Log T.D. 5448 - hole had filled some) B & A Plugging compl 1-22-56.