

Cowley Co

Map No. KANSAS Sec. 10 Twp. 30 R. 4

Well No. 1 Harnaday

Shawver & Sutter Company

Contractor

FIRST REPORTS

SECTION PLAT

_____ Ft. from N. Line

250

_____ Ft. from S. Line

_____ Ft. from E. Line

600

_____ Ft. from W. Line

Location _____

Rig up _____

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

AUG 20 1925

CHAS. L. SHERWOOD

192

Scout

Cowley 20

Map No. *K11* KANSAS Sec. *10* Twp. *30* R. *4*

Well No. *1* *Harnaday*
Shawver & Sutton Company

Contractor

COMPLETED

SECTION PLAT

----- Ft. from N. Line
250
----- Ft. from S. Line
----- Ft. from E. Line
550
----- Ft. from W. Line

		o	

ABANDONED

Location -----

Rig up -----

Drilling and Remarks:

Show oil 2755'
Small show 2850'
Dry & abo
L.O. 2855'

RECORD

Cased ----- in., ----- ft.
Sand -----
Gas -----
Oil -----
Total Depth *2855'*

PRODUCTION

1st 24 hrs. Nat. -----
1st 24 hrs. after shot -----
Gas ----- Cu. Ft.
Dry Hole
Abandoned

Date

NOV 13 1925

CHAS. L. SHERWOOD

Cowley
10

K11
MAP No. **KANSAS** SEC. 10 TWP. 30S R. 4E

WELL No. 1 Homaday
Shawnee COMPANY

CONTRACTOR

ABANDONED

SECTION PLAT

_____ FT. FROM N. LINE
 _____ FT. FROM S. LINE
 _____ FT. FROM E. LINE
 _____ FT. FROM W. LINE

RECORD

LOCATION _____

CASED _____ IN., _____ FT.

RIG UP _____

SAND _____

DRILLING AND REMARKS:

GAS _____

OIL _____

TOTAL DEPTH 2855

PRODUCTION

1ST 24 HRS. NAT. _____

1ST 24 HRS. AFTER SHOT _____

GAS _____ CU. FT.

DRY HOLE

ABANDONED

DATE

11/11 192 5

SCOUT