

SEC. 14 STATE Kansas COUNTY Edwards
 TOR BK R OR SUR 26 SURVEY 187
 14
 COMM. APR. 19, 1926 COMP. 2-12-37
 WELL NO. 1 LOCATION IN SECTION C SE SE
 LEASE Donovan
 COMPANY Elwell & Stanolind
 ELEV. 2167 CASING RECORD
 I. PROD. DPA

Form 265 - For Sale by MID-WEST PRINTING CO., Tulsa.

Depth (ft)	Notes
0	Rotary
1	15" 212
2	S.D. W.B.C. at 250' T.D., 15" = 212'
3	
4	
5	
6	
7	
8	
9	
10	
11	Stop washed pump 1100-1300, then Skipped washing to 2100' & washed 2100' or down -> HSB
12	T. Ark. = 1168 s (STAN) B. " = 1196 s + 272 s = BA 2167 No. BA = 40' below HSB Shell # Johnson
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	lost circ. of 25 1/2" 60 dly 2560 4-30-36
26	
27	
28	
29	
30	
31	
32	
33	lost circ. at 3282' 5-4-36 HSB Carrying 10 1/2" to 11 3/4" Mud lost circ. at 3300' + " " 3300-3560'
34	
35	7 Top 34 1/2 2167 11293
36	
37	
38	
39	dly 3881 5-8-36 80 circ. at 3900' BK Hill of well Cased 3900-20' + recov. 7' case
40	drilled 3' = black sh (3920-23) " 3' = broken ls (3923-26) " 4' = lime (3926-30) 5-2-36 B. Black sh = 3900' (Garvin Taylor) dly 3943 5-10-36 " " L.P. Call HSB
41	Started casing at 4015 5 PM. 5-10-36 L.P. call Garvin Taylor HSB HPW-4070
42	Cased 4015-35' + recov. 20' case 4015-28' black platy sh 30 inc. w. 4028-32' dense tan very fine lime 8 430-38 4022-32' calc. Green-Green sh Going into casing down L.P. call Noon 5-11-36 HSB Fishing at 4135 with 2500' wire line 71 12ML in hole - 6-8-36
43	Drilling 4197 in Oswald casing A HPW. No shows. E.A.H. 6-12-36 dly 4221 6-13-36 18W-4100-13 24W-4113-18 72 HPW-4130-38
44	
45	could make no more standard tool hole below 4445' so ran 7" 4445' 5/8 7-7-36 HSB 7" did not have W.S.O. so drilled to 4462' Use set 7" 4462' oil battery & got good W.S.O. Bailed hole dly 4471 7-16-36 Taylor HSB 4500 = 4506 SLM Garvin Taylor HSB
46	Top white chat = 4540' (Taylor on well) 3.3 GOS 4545-47 7-12-36 white sand 4557-67 30 4558-59 4567 for New bull ropes 7-20-36 will start up 7-21-36 SLM-4590 = 4578
47	fsd at 4580' 7-27-36 Heidig T.D. 4585, lost straw of tools; lost samp 4580 pulled 7" pipe + New dly by tools dly 4597 for New bull ropes (Tools 48' long) 4647 KWLB Garvin Taylor Packer 8-7-36 HSB Did not get sample 4580-85 when tools were lost
48	Drilled by tools + made 5' to 4580' T.D. when lost more tools. on 5-10-36 had four strings of tools in the hole; so decided to skid rig & drill new hole by rotary to approx. 4580' T. Simpson. 4790. KWLB Garvin Taylor - Stanolind 9-11-36 HSB
49	more in rotary; Set whipstock; drilled new hole beginning at about 4100' (only overage of 2" off vertical to 4590') TSL 4872 KWLB.
50	T.D. New rotary hole = 4587' 4590' set 5 1/2" pipe at 4587' + ROST 11-10-36 HSB 4590 = 4578 SLM; 5' = 4574c S.S.O. 4672-78' (1 80 Men Wt - Taylor) T. Simpson Green sh = 4795 (scout) Tsp = 4787s 2167 - 2620s 800' wtr 4805-10' (wtr = 4808' log) dly in hard line at 4817' 12-19-36 (STAN) new 4800 HSB Big inc. w wtr = 4832' (Garvin Taylor)
51	dly 4861 in dark sh 12-22-36 (Taylor) Base Simpsons Green sh = 4871 (driller) dly in cherty ls = 4890, carrying a HPW Garvin Taylor HSB 12-28-36 4942; with 70' case in hole 1-2-36 Garvin Taylor - HSB r. 511 4872 (scout) 4944: 4950 SLM; set 1 1/2" of 4" liner at 4961 dly 4962 - 2-10-37
52	dly 4980. 2-12-37 (shale break 4978-80) still carrying a HPW. HSB
53	Pulled tools at 4982, tools caught in liner & lifted liner, leaving in bed case Jerry Simpson on well; P.M. 2-12-37 HSB S.D. 4984' with 47' casing in hole Contractor anxious to abandon Simpson on well HSB T.D. 4984 DPA 2-17-37
54	
55	
56	
57	
58	
59	
60	