


Map No. _____ Sec. 29 Twp. 28 R. 4Well No. 18. J. P. Love Farm __________Empire_____
Company

NORTH



SOUTH

Location _____

Rig Up _____

Drilling Remarks:

Drilling Remarks:

RECORD

Cased _____ in. _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ cu. ft

Dry Hole _____


Abandoned _____

Map No. _____ Sec. 29 Twp. 28 R. 4Well No. 18. J. P. Love Farm _____Company Caspien

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up ✓ _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

8-28-7, 1917 Lautz Scout


Map No. _____ Sec. 29 Twp. 28 R. 4

Well No. 18 Love Farm _____

Engine Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

1320

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


10/9, 1917 Carley Scout _____

Map No. _____ Sec. 29 Twp. 28 R. 4
Well No. 18 _____ Farm _____
_____ Engine Company

NORTH

WEST

EAST



SOUTH

Location _____
Rig Up _____
Drilling and remarks
1825

RECORD

Cased _____ in. _____ Ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION


1st 24 hrs. Nat. _____
1st 24 hrs. after shot _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____

Date 10/17, 1912, Condy Scout

Map No. _____ Sec. 29 Twp. 28 R. 4Well No. 18 Rose Farm __________Engine Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2147

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/24, 1917 C. C. C. Scout

Map No. _____ Sec. 29 Twp. 28 R. 4Well No. 18 Farm _____

_____ Company

NORTH

WEST

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2430

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


10/31, 1912 _____ Scout

Map No. _____ Sec. 29 Twp. 28 R. 4Well No. 18 Rose Farm _____

Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

Est at
700 Barrels
Natural

RECORD

Cased _____ in. _____ Ft.

Sand 2454-2460

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

11-7, 1917 Candell Scout

L1002
 Map No. 111 Sec. 29 Twp. 28 R. 4
 Well No. 18 - Look Farm _____
Empire Company _____

NORTH

WEST	218							EAST
	018	67						
	Which location is correct?							

SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____

Date _____

_____, 191____. _____ Scout

Cardiff