


Map No. _____ Sec. 4 Twp. 27 E. 5Well No. #1 Mittle Farm _____Atlas Petro Company _____

NORTH

WEST

EAST



SOUTH

Location _____

Rig Up _____

Drilling Remarks:

Drilling Remarks:

RECORD

Cased _____ in. _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 h's. after shot _____

Gas _____ cu. ft


Dry Hole _____

Abandoned _____

Map No. _____ Sec. 5 Twp. 27 R. 5Well No. 1 Huttler Farm
Atlas Petro Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up ☒ _____

Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

7/12, 1912 Landry Scout

FIRST REPORT

FIRST REPORT


Map No. _____ Sec. 5 Twp. 27 R. 5

Well No. 17 miles Farm _____

Atlas Pet Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

350'

RECORD

Cased _____ in _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

7/17, 1917 Candys Scout

Map No. _____ Sec. 5 Twp. 27 R. 5Well No. 1 Kuttel Farm _____Atlas Petro Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig up _____

Drilling and remarks:

This section
No. wrong
also location
was originally
located as above
but later changed

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st. 24 hrs. Nat. _____

1st. 24 hrs. after shot. _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

7/27, 1917, C. Condiff Scout

Map No. _____ Sec. 4 Twp. 27 R. 5Well No. 1 Middle Farm
Atlas Petro Company

NORTH

WEST



EAST

SOUTH

Location _____

Rig up _____

Drilling and remarks:

850

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st. 24 hrs. Nat. _____

1st. 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

7/27 1917 Cordiff Scout

Map No. _____ Sec. 4 Twp. 27 R. 5

Well No. 18 Nettle Farm
Atlas Petro Company

NORTH

WEST

EAST

SOUTH

RECORD

Location _____

Cased _____ in. _____ Ft.

Rig up _____

Sand _____

Drilling and Remarks:

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

8/1, 1917, C. C. C. C. Scout

Map No. _____ Sec. 4 Twp. 27 R. 5Well No. 1 Little Farm _____Altos Petros Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2440

RECORD

Cased _____ in _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

8/7, 1917 Conroy Scout

Map No. _____ Sec. 4 Twp. 27 R. 5Well No. 1. Nuttle Farm _____Atlas Company _____

NORTH

WEST

EAST

SOUTH

COMPLETED

Location _____

Rig Up _____

Drilling and remarks

Top of sand
2537. Hole
full of water
in top

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole ☒ _____Abandoned 2542'

Date

8-21, 1917 Lacy Scout