


Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. 1 Swartz Farm _____
Proquain Company _____

NORTH

WEST

EAST



SOUTH

Location _____
Rig Up _____
Drilling and remarks _____

RECORD

Cased _____ in _____ Ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
1st 24 hrs. after shot _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____

FIRST REPORT


Date

7/12, 1917 Candy Scout

Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. 1 Smartz Farm _____
Proquios Company

NORTH



SOUTH

Location ✓ _____
Rig up _____
Drilling and remarks:

RECORD

Cased _____ in. _____ Ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION


1st. 24 hrs. Nat. _____
1st. 24 hrs. after shot. _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____

Date 7/27 1917 W. Conroy Scout

Map No. _____ Sec. 25 Twp. 27 R. 5

Well No. 1 Swartz Farm _____
propolis Company _____

NORTH



SOUTH

Location _____

Rig up _____

Drilling and remarks:

Wrong Location

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st. 24 hrs. Nat. _____

1st. 24 hrs. after shot. _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date 7/30 1917 Cardiff Scout


Map No. _____ Sec. 25 Twp 27 R. 6

Well No. 1 Amity _____ Farm _____

_____ Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig up _____

Drilling and remarks:

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st. 24 hrs. Nat. _____

1st. 24 hrs. after shot. _____

Gas _____ Cu. Ft.

Dry Hole _____


Abandoned _____

Date 7/30 1917

Cordell Scout

Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. 1 Swartz Farm _____
Prognosis Company _____
NORTH



Location _____
Rig up _____
Drilling and Remarks:

RECORD

Cased _____ in. _____ Ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION


1st 24 hrs. Nat. _____
1st 24 hrs. after shot _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____

Date 8/1, 1917, Prognosis Scout

Map No. _____ Sec. 25 Twp. 27 R. 5

Well No. _____ Farm _____
Company _____

NORTH



SOUTH

Location _____
Rig Up _____
Drilling and remarks _____

RECORD

Cased _____ in. _____ Ft.
Sand _____
Gas _____
Oil _____
Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
1st 24 hrs. after shot _____
Gas _____ Cu. Ft.
Dry Hole _____
Abandoned _____

Date _____

191 _____

W. P. Bram
Scout

Shouldn't this be in
 Sec. 25 - T. 27 - R. 6 - 9



RECORD
 Cased in Ft. _____
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION
 1st 24 hrs. Nat. _____
 1st 24 hrs. after shut _____
 Gas Cu. Ft. _____
 Dry Hole _____
 Abandoned _____

Location _____
 Rig Up _____
 Drilling and remarks _____


Date _____

Scale _____

Map No. K11 Sec. 25 Twp. 22 R. 5

Well No. 1 Swartz Farm
Progressive Company

NORTH



Location -----
Rig Up -----
Drilling and remarks

RECORD

Cased ----- in. ----- Ft.
Sand -----
Gas -----
Oil -----
Total Depth -----

PRODUCTION

1st 24 hrs. Nat. -----
1st 24 hrs. after shot -----
Gas ----- Cu. Ft.
Dry Hole -----
Abandoned -----

Date


7/27, 1917 Carby Scout

Map No. ----- Sec. 25 Twp. 27 R. 6

Well No. 1 Swartz Farm
Prognis Company

NORTH

WEST



EAST

SOUTH

Location -----
Rig Up -----
Drilling and remarks

360

RECORD

Cased ----- in. ----- Ft.
Sand -----
Gas -----
Oil -----
Total Depth -----

PRODUCTION

1st 24 hrs. Nat. -----
1st 24 hrs. after shot -----
Gas ----- Cu. Ft.
Dry Hole -----
Abandoned -----

Date 8/15, 1917 Carney Scout


Map No. KA Sec. 45 Twp. 27 R. 6

Well No. L. S. Swartz Farm
Boyer Company

NORTH

WEST

EAST



SOUTH

Location -----
 Rig Up -----
 Drilling and remarks

at 950

RECORD

Cased ----- in. ----- Ft.
 Sand -----
 Gas -----
 Oil -----
 Total Depth -----

PRODUCTION

1st 24 hrs. Nat. -----
 1st 24 hrs. after shot -----
 Gas ----- Cu. Ft.
 Dry Hole -----
 Abandoned -----


Date 8-21-1917 Lautz Scout

Map No. ----- Sec. 25 Twp. 27 R. 6

Well No. 1 Farm -----
Proprietor Company -----

NORTH

WEST



EAST

SOUTH

Location -----
Rig Up -----
Drilling and remarks

1470

RECORD

Cased ----- in. ----- Ft.
Sand -----
Gas -----
Oil -----
Total Depth -----

PRODUCTION

1st 24 hrs. Nat. -----
1st 24 hrs. after shot -----
Gas ----- Cu. Ft.
Dry Hole -----
Abandoned -----

Date


9/5, 1917 Carney Scout

Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. _____ Farm _____

_____ Company _____

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks

1775

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

9/2, 1917

Conroy


Scout

Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. 1500 Farm _____

Progressive Oil Company

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks

1920

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

9/19, 1917 Carney Scout

Map No. ----- Sec. 25 Twp. 27 R. 6

Well No. 1 Survey Farm -----
Prognostic Company -----

NORTH



SOUTH

Location -----

Rig Up -----

Drilling and remarks

2130

RECORD

Cased ----- in. ----- Ft.

Sand -----

Gas -----

Oil -----

Total Depth -----

PRODUCTION

1st 24 hrs. Nat. -----

1st 24 hrs. after shot -----

Gas ----- Cu. Ft.

Dry Hole -----


Abandoned -----

Date

9/27, 1911 Conley Scout

Map No. _____ Sec. 25 Twp. 27 R. 6
Well No. 10000 Farm _____
proprietor's oil Company _____

NORTH



SOUTH

Location _____

Rig Up _____

Drilling and remarks

2260

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/2, 1917, Candey

Scout


Map No. ----- Sec. 25 Twp. 27 R. 6

Well No. 1 Swartz ----- Farm

Prognosis ----- Company

NORTH

WEST



EAST

SOUTH

RECORD

Location -----

Cased ----- in. ----- Ft.

Rig Up -----

Sand -----

Drilling and remarks

Gas -----

Oil -----

Total Depth -----

2320

PRODUCTION

1st 24 hrs. Nat. -----

1st 24 hrs. after shot -----

Gas ----- Cu. Ft.

Dry Hole -----

Abandoned -----


Date

10/9, 1917 Scout Scout

Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. 10000 _____ Farm _____
Prognosis _____ Company _____

NORTH



SOUTH

Location _____

Rig up _____

Drilling and remarks:

*Shut Down
 for water
 2350*

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st. 24 hrs. Nat. _____

1st. 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

10/17 1917 Carroll Scout

Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. Summit _____ Farm _____
Argonite _____ Company _____

NORTH

WEST

								0

EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

2640

RECORD

Cased _____ in. _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


10/24/1917 _____ Scout

Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. 1 Swartz Farm _____
proprietor Company _____

NORTH

WEST



EAST

SOUTH

Location _____

Rig Up _____

Drilling and remarks

*Shut down
2840*

RECORD

Cased _____ in _____ Ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____


Date

10/31, 1917 Conroy Scout

Map No. _____ Sec. 25 Twp. 27 R. 6

Well No. 1 Swartz Farm _____
proprietor Company _____

NORTH



SOUTH

RECORD

Location _____

Cased _____ in. _____ Ft.

Rig Up _____

Sand _____

Drilling and remarks

Gas _____

Oil _____

Total Depth _____

D 2840

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date


11-7, 1917 Cordy Scout

Map No. ----- Sec. 25 Twp. 27 R. 6

Well No. 1 Swinity Farm
Prognosis Company

NORTH

WEST



EAST

SOUTH

Location -----
 Rig Up -----
 Drilling and remarks

LD 2840

RECORD

Cased ----- in. ----- Ft.
 Sand -----
 Gas -----
 Oil -----
 Total Depth -----

PRODUCTION

1st 24 hrs. Nat. -----
 1st 24 hrs. after shot -----
 Gas ----- Cu. Ft.
 Dry Hole -----
 Abandoned -----

Date

11-14, 1917 Scout Scout

Map No. _____ Sec. 25 Twp. 27 R. 6


Well No. 1 Smoky Farm _____

Progress Company _____

NORTH

WEST

EAST



SOUTH

RECORD

Location _____

Cased _____ in. _____ Ft.

Rig Up _____

Sand _____

Drilling and remarks

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

*Shut down
2840*


Date

11/21, 1917 Candey Scout

Map No. _____ Sec. 35 Twp. 27 R. 6

Well No. 1 Swartz Farm _____
proprietor Company _____

NORTH



SOUTH

Location _____
 Rig Up _____
 Drilling and remarks _____

*Shut Down
2840*

RECORD

Cased _____ in. _____ Ft.
 Sand _____
 Gas _____
 Oil _____
 Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____
 1st 24 hrs. after shot _____
 Gas _____ Cu. Ft.
 Dry Hole _____
 Abandoned _____


Date

11/28, 191 2 Cuddy Scout

Map No. *K111* Sec. *25* Twp. *27* R. *6*

Well No. *1 Swartz* Farm
Proquidis Company

NORTH



SOUTH

Location -----
 Rig Up -----
 Drilling and remarks

Dry & Abandoned

2808'

RECORD

Cased ----- in. ----- Ft.
 Sand -----
 Gas -----
 Oil -----
 Total Depth -----

PRODUCTION

1st 24 hrs. Nat. -----
 1st 24 hrs. after shot -----
 Gas ----- Cu. Ft.
 Dry Hole -----
 Abandoned -----

Date *10/5/1917* Scout *Cooper*