


Rice

KANSAS

Section 22 Township 18 Range 9-4

Well No. 1 Leach

Company Western Kansas O&R et al



KANSAS

Rice

Sec. 22 Twp. 18 R. 9-W

Well No. #1 Leach Farm


Western Kansas O & R et al Company

Ft. from N. Line

330 Ft. from S. Line

Ft. from E. Line

330 Ft. from W. Line



1938	REPORT
6/8	Drlg. 1175'.
6/17	Lans. 2895'. S.O. 2970-75'.
	Drlg. 3145'.
6/22	Cong. 3252'.
	S. S. O. 3252-62'.
	Arb. 3323-62'.
	T.D. 3362'.
	No shows.
	ABANDONED
	ABANDONED

Rice

KANSAS

Map No. 45 Sec. 22 Twp. 18 R. 9W

Well No. 1 Leach

Western Kansas O & R etal Company

Contractor

FIRST REPORT

SECTION PLAT

SW/C

_____ Ft. from N. Line

330 Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

0			

Location _____

Rig up _____

Drilling and Remarks:

Drlg. 1175

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JUN 8 - 1930 19

H. D. Hatfield Scout

Rice

KANSAS

Map No. 45 Sec. 22 Twp. 18 R. 9W

Well No. 1 Leach

Western Kansas O & R et al Company

Contractor

ABANDONED

SECTION PLAT

SW/C

_____ Ft. from N. Line

330 Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

Location _____

Rig up _____

Drilling and Remarks:

Cong 3252
SS, O 3252-62
ARB 3323-62
no shows
DVA

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 3362

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JUN 22 1938 19

H. D. Hatfield Scout