


KANSAS

Barton

Section 26 Township 20 Range 14WWell No. #1 BondurantCompany Texas

Sec. 26 Twp. 20 R. 14W

Well No. #1 Bondurant Farm

Texas

Pritchard

Company

 Ft. from N. Line


990

 Ft. from S. Line

 Ft. from E. Line

990

 Ft. from W. Line



NE SW NE

E. W. 1900

SOUTH

1945

R E P O R T

3/7

R U R

3/14

8" @ 814
Drlg 1460

3/23

Lans 3278
Drilling 3472'

3/29

Arb 3550-51
TD 3551

4/5

5" @ 3541 RUST
500 acid No help
Drlg. 3591'

4/12

TD 3591' S.D.

4-18

Arbuckle 3550'
5" at 3541'
Total Depth 3598'

ABANDONED

Pool Name PritchardMap No. 82 Sec. 26 Twp. 20 R. 14WWell No. 1 BondurantTexas


Company _____

FIRST REPORT

Contractor _____

NE SW NE

SECTION PLAT



_____ Ft. from N. Line

990 Ft. from S. Line

_____ Ft. from E. Line

990 Ft. from W. LineBarton

Location _____

Rig up _____

Drilling and Remarks:

RUR

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

MAR 7 1945 19S. J. LEWIS

Scout

Kansas Pool Name PritchardMap No. 82 Sec. 26 Twp. 20 R. 14WWell No. 11 BondurantTexas

Company

ABANDONED

Contractor

NE SW NE

E. 1900

SECTION PLAT

		6	

 Ft. from N. Line990 Ft. from S. Line Ft. from E. Line990 Ft. from W. LineBarton CountyLocation Rig up

Drilling and Remarks:

*Cor 43550**5" 3541*

RECORD

Cased in., ft.Sand Gas Oil Total Depth 3588

PRODUCTION

1st 24 hrs. Nat. 1st 24 hrs. after shot Gas Cu. Ft.Dry Hole Abandoned

Date

APR 18 1945

19

S. J. LEWIS

Scout