

BEE FORMATION TESTING CO., INC.

P. O. BOX 491

GREAT BEND, KANSAS

DATE March-10-1955.N^o 747CUSTOMER'S
ORDER NO. _____NAME OF COMPANY Colorado - oil & Gas - Co. Box 1030ADDRESS TO MAIL INVOICE Haven - Kansas. Wichita

ADDRESS TO MAIL PRESSURE CHARTS _____

LEASE Hertig WELL NO. 1 COUNTY Pawnee STATE KansasTESTER J. O. Heathcock APPROVED James R. JockDRILL STEM TEST NO. 4 SUCCESSFUL NO. 4 MIS-RUN NO. (miss)SIZE HOLE 7 7/8 TOOL JT. 4 1/2 f.h.RUBBER SIZE 7" 29 1/2 x 2 5/8 TEST TOOL SIZE 4 5/8PACKER SET AT 4296. - ANCHOR SIZE 4 1/2TOTAL DEPTH WELL 4310 LENGTH ANCHOR 14PRESSURE RECORDER CAP. 3500- 3500 DRILL PIPE RUN: DRY All- WITH FLUID _____

RESULTS:

PACKER SET 1:05 A.M. TOOL OPEN 1:10 A.M. TOOL OPEN 1/4. HRS.BLOW weak 10 min-RECOVERY 30 ft Rotary mud-SHUT IN PRESSURE TIME 1 hr. MUD WT. 10.3# VIS. 45 sec. WATER LOSS 12.4 cc-BHP 0 IFP 0 FFP 0 HYDROSTATIC HEAD 2450.EXTRA EQUIPMENT None Run JARS ----- NO. ----- SIZE -----OPERATOR TIME 10 TOOL RENTAL TIME _____

BEE FORMATION TESTING CO., INC.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.

