

Kansas **12-76** **Twinn Western**
 Hodge man **Trusher** WELL NO. **1**
 BLOCK SURVEY
 SEC. **3** **4465**
 T. **24S** R. **23W** TOTAL DEPTH
 COMMENCED
 COMPLETED
 REMARKS **no film.**
 ALTITUDE **2259 K13**
 PRODUCTION **D. & H.**

Arky 2 1450

Sample Start @ 3700'

3700	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	4677. Sh. 3748
3800	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	Toronto 3764
3900	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	LS 3801
4000	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	
4100	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	
4200	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	BKC 4162
4300	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	Pawnee 4251
4400	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	4 Scott 4329
4500	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	PBC 4403
4600	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	MISS 4416
	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	T.O. 4465
	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	no Tests
	Wh. g. & sh. suc. to fix. soft. por. for dy. sh. etc.	853