

Map No. _____ Sec. 4 Twp. 26 R. 5Well No. 10 Jimmy _____ Farm
Empire _____ Company

NORTH

WEST

EAST

COMPLETED

SOUTH

Location _____

Rig Up _____

Drilling Remarks:

Drilling Remarks:

RECORD

Cased _____ in. _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shct _____

Gas _____ cu. ft.

Dry Hole _____

Abandoned _____

Map No. K14 Sec. 4 Twp. 26 R. 5
 Well No. 10 Fumney
Empire Company
 Contractor

NORTH

WEST

EAST

FIRST REPORT

SOUTH

9905-E

Location _____

Rig up ☒ _____

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

April 8 1919 Clyde Scout

Map No. K14 Sec. 4 Twp. 26 R. 5Well No. 10 FinneyCompany Empire

Contractor _____

NORTH

WEST

EAST

COMPLETED

SOUTH

9905-E

Location _____

Rig up _____

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand 2538-2571

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. 10 bbls

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

Pyle

191 9

Scout