

Map No. Kansas Sec. 3 Twp. 22 R. 12
 Well No. 1 Teannet Farm
Lamar & Hane Company

NORTH

WEST

EAST

SOUTH

14

Location _____

Drilling Remarks

Rig Up _____

Drilling Remarks

RECORD

Cased _____ in. _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ cu. ft.

Dry Hole _____

Abandoned _____

Map No. Kansas Sec. 3 Twp. 22 R. 12

Well No. 1 Jeannet Farm
Lamar & Hane Company

NORTH

WEST

EAST

SOUTH

Ft. from N. Line

1120 Ft. from S. Line

200 Ft. from E. Line

Ft. from W. Line

Date

REPORT

12/23 Location

12/31

~~1926~~

1/8

1/11

2/20

2/27

3/4 Rig

3/10

2/17

2/24

3/5

3/10

3/18 S.D. 400'

3/25 J.D. 400. skidding rig

4/1

4/7

4/14 Drlg 900

4/21 Top sd. 1747-1767' Drlg 1840.

4/29 Sd. 1747-1767. Dry. J.D.

D-A.

Map No. KANSAS Sec. 3 Twp. 22 R. 12

Well No. 1 Leather
Leaman & Hine Company

Adam & Hane

Company

SECTION PLAT

-----Ft. from N. Line

1/20

Ft. from S. Line

200

Ft. from E. Line

-----Ft. from W. Line

FIRST REPORTS

	6		

Location -----

Rig up -----

Drilling and Remarks:

RECORD

Cased-----in., ----- ft.

Sand -----

Gas _____

Oil_____

Total Depth_____

PRODUCTION

1st 24 hrs. Nat. -----

1st 24 hrs. after shot_-----

Gas_____Cu. Ft.

Dry Hole_____

Abandoned-----

Date _____

DEC 23 1925

CHAS. L. SHERWOOD

192

Scout

Greenwood
 Map No. **K21 KANSAS** Sec. **3** Twp. **22** R. **12**

Well No. **1 Jeanne**
Lamar & Hone Company

Contractor

COMPLETED

SECTION PLAT

_____ Ft. from N. Line

1120 _____ Ft. from S. Line

200 _____ Ft. from E. Line

_____ Ft. from W. Line

ABANDONED

Location _____

Rig up _____

Drilling and Remarks:

0 2 45
1847

RECORD

Cased _____ in., _____ ft.

Sand *1747-1767 dry*

Gas _____

Oil _____

Total Depth *1847*

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole ☒

Abandoned ☒

Date

APR 28 1926

CHAS. L. SHERWOOD

192

Scout