

ma

COPY

STATE CORPORATION COMMISSION OF KANSAS
OIL & GAS CONSERVATION DIVISION
WELL COMPLETION FORM
ACD-1 WELL HISTORY
DESCRIPTION OF WELL AND LEASE

API NO. 15- 131-201630000

County Nemaha

20' W of S/2 SE - NW Sec. 23 Twp. 35 Rng. 13 XXX

2970 Feet from S/N (circle one) Line of Section

3320 Feet from E/W (circle one) Line of Section

Footages Calculated from Nearest Outside Section Corner:
NE, (E) NW or SW (circle one)

Lease Name Pfrang Well # 1

Field Name Wildcat

Producing Formation N/A

Elevation: Ground 1342 KB 1347

Total Depth 2262 PBDT 2262

Amount of Surface Pipe Set and Cemented at 320' Foot

Multiple Stage Cementing Collar Used? Yes No

If yes, show depth set _____ Feet

If Alternate II completion, cement circulated from _____

feet depth to _____ w/ _____ sx cat.

Drilling Fluid Management Plan D&A JK 10-23-96
(Data must be collected from the Reserve Pit)

Chloride content _____ ppm Fluid volume _____ bbls

Dewatering method used _____

Location of fluid disposal if hauled offsite: _____

Operator Name Brandt Production Company, Inc.

Lease Name Pfrang License No. 5360

NW Quarter Sec. 23 Twp. 3 S Rng. 13 E/W XXX

County Nemaha Docket No. _____

Operator: License # 5360

Name: Brandt Production Company, Inc.

Address 107 N. Market, #914

City/State/Zip Wichita, KS 67202

Purchaser: _____

Operator Contact Person: Earl O. Brandt

Phone (316) 267-4335

Contractor: Name: Summit Drilling Company

License: 30141

Wellsite Geologist: Earl O. Brandt

Designate Type of Completion
 New Well Re-Entry Workover

Oil SWD SIOW Temp. Abd.
 Gas ENHR SIGW
 Dry Other (Core, WSW, Expl., Cathodic, etc)

If Workover/Re-Entry: old well info as follows:

Operator: _____

Well Name: _____

Comp. Date _____ Old Total Depth _____

Deepening Re-perf. Conv. to Inj/SWD
 Plug Back PBDT
 Commingled Docket No. _____
 Dual Completion Docket No. _____
 Other (SWD or Inj?) Docket No. _____

9-5-95 9-10-95 9-10-95

_____ Date Reached TD _____ Completion Date _____

INSTRUCTIONS: An original and two copies of this form shall be filed with the Kansas Corporation Commission, 200 Colorado Derby Building, Wichita, Kansas 67202, within 120 days of the spud date, recompletion, workover or conversion of a well. Rule 82-3-130, 82-3-106 and 82-3-107 apply. Information on side two of this form will be held confidential for a period of 12 months if requested in writing and submitted with the form (see rule 82-3-107 for confidentiality in excess of 12 months). One copy of all wireline logs and geologist well report shall be attached with this form. ALL CEMENTING TICKETS MUST BE ATTACHED. Submit CP-4 form with all plugged wells. Submit CP-111 form with all temporarily abandoned wells.

All requirements of the statutes, rules and regulations promulgated to regulate the oil and gas industry have been fully complied with and the statements herein are complete and correct to the best of my knowledge.

Signature Earl O. Brandt

Title President Date 10/27/95

Subscribed and sworn to before me this 27 day of October 19 95.

Notary Public Barbara June Brandt

Date Commission Expires 2-28-96

BARBARA JUNE BRANDT
NOTARY PUBLIC
STATE OF KANSAS
My Appt. Exp. 2-28-96

K.C.C. OFFICE USE ONLY
F Letter of Confidentiality Attached
C Wireline Log Received
C Geologist Report Received
Distribution
 KCC SWD/Rep NGPA
 KGS Plug Other (Specify)

106

1995

Operator Name Brandt Production Co., Inc.

Lease Name Pfrang

Well # 1

449414

Sec. 23 Twp. 3S Rge. 13

County Nemaha

East
 West

INSTRUCTIONS: Show important tops and base of formations penetrated. Detail all cores. Report all drill stem tests giving interval tested, time tool open and closed, flowing and shut-in pressures, whether shut-in pressure reached static level, hydrostatic pressures, bottom hole temperature, fluid recovery, and flow rates if gas to surface during test. Attach extra sheet if more space is needed. Attach copy of log.

Drill Stem Tests Taken (Attach Additional Sheets.)	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<input checked="" type="checkbox"/> Log Formation (Top), Depth and Datum Name Top Datum Howard 403 +944 Top 446 +901 Heebner 651 +696 Lansing 813 +534 Kansas City 877 +470 Base Kansas City 1064 +278 Hunton 1296 +51 Maquoketa 1887 -540 Viola 1950 -603 Simpson Sand 2213 -866	<input type="checkbox"/> Sample
Samples Sent to Geological Survey	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Cores Taken	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Electric Log Run (Submit Copy.)	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
List All E.Logs Run:			

CASING RECORD <input type="checkbox"/> New <input checked="" type="checkbox"/> Used							
Report all strings set-conductor, surface, intermediate, production, etc.							
Purpose of String	Size Hole Drilled	Size Casing Set (In O.D.)	Weight Lbs./Ft.	Setting Depth	Type of Cement	# Sacks Used	Type and Percent Additives
Surface	12 1/4	8 5/8	204	320 1/2		175sx	

ADDITIONAL CEMENTING/SQUEEZE RECORD				
Purpose:	Depth Top Bottom	Type of Cement	#Sacks Used	Type and Percent Additives
<input type="checkbox"/> Perforate				
<input type="checkbox"/> Protect Casing				
<input type="checkbox"/> Plug Back TD				
<input type="checkbox"/> Plug Off Zone				

Shots Per Foot	PERFORATION RECORD - Bridge Plugs Set/Type		Acid, Fracture, Shot, Cement Squeeze Record	
	Specify Footage of Each Interval Perforated		(Amount and Kind of Material Used)	Depth

TUBING RECORD							
Size	Set At	Packer At	Liner Run	<input type="checkbox"/> Yes <input type="checkbox"/> No			
Date of First, Resumed Production, SWD or Inj.		Producing Method <input type="checkbox"/> Flowing <input type="checkbox"/> Pumping <input type="checkbox"/> Gas Lift <input type="checkbox"/> Other (Explain)					
Estimated Production Per 24 Hours		Oil <u>N/A</u> Bbls.	Gas <u>N/A</u> Mcf	Water <u>N/A</u> Bbls.	Gas-Oil Ratio	Gravity	

Disposition of Gas: Vented Sold Used on Lease (If vented, submit ACO-18.)

METHOD OF COMPLETION: Open Hole Perf. Dually Comp. Commingled Other (Specify) _____

Production Interval: _____