


Russell

Form 51-5M-11-31-Palace

Map No. **KANSAS** Sec. 4 Twp. 14 R. 15^w

Well No. 2 Benco Farm
Central Pet. Company

NORTH



SOUTH

Location _____

Drilling Remarks _____

Rig Up _____

Drilling Remarks _____

RECORD

Cased _____ in. _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ cu. ft.

Dry Hole _____

Abandoned _____

Russell

Map No. KANSAS Sec. 4 Twp 14 R. 15^W


Well No. 2 Benso Farm
Central Pet. Company

330 Ft. from N. Line

_____ Ft. from S. Line

990 Ft. from E. Line

_____ Ft. from W. Line



Date

REPORT

1934	
6/27	Location
7/5	—
7/12	Moving in
7/19	Rign up
7/26	Spud
8/2	20" 20 15" 415 H770 320 Dly 580
8/9	" 1980 10" 931
8/16	8" 2305 2370 WR 8"
8/23	Dly 2900 678 2545
8/30	WR 6" 2918
9/6	—
9/13	Drwell 3036-74 TD 3076 Pay 3057-74 1000 acid
9/20	—
9/26	Drwell 3036 Oil 3057-74 TD 3076 1000 acid 195 Bbls.

COMPLETED

Map No. 72 Sec. 4 Twp. 14 R. 15W

Well No. 2-Benso

Central Pet. Company

Contractor

FIRST REPORTS SECTION PLAT

330 Ft. from N. Line

_____ Ft. from S. Line

990 Ft. from E. Line

_____ Ft. from W. Line

	0		

Location ✓

Rig up _____

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date 6-27-37
19

ORVAL MANNSCHRECK
Scout

Map No. 72 Sec. 4 Twp. 14 R. 15W

Well No. 2-Benso

Central pit

Company

Contractor

COMPLETED

SECTION PLAT

	0		

330 Ft. from N. Line

_____ Ft. from S. Line

990 Ft. from E. Line

_____ Ft. from W. Line

Location _____

Rig up _____

Drilling and Remarks:

1000 acid

195 hrs

RECORD

Cased _____ in., _____ ft.

Sand Oswald 3036

Gas _____

Oil 3057-74

Total Depth 3076

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

9-26-37 19

ORVAL MANNSCHRECK

Scout