

BEE FORMATION TESTING CO.

TEST TICKET

DATE 1-3-56

P. O. BOX 491

GREAT BEND, KANSAS



N^o 1340CUSTOMER'S
ORDER NO.NAME OF COMPANY C. R. A.ADDRESS TO MAIL INVOICE Box 765 Great Bend KansADDRESS TO MAIL PRESSURE CHARTS SAMELEASE Harbours WELL NO. C-4 COUNTY ness STATE KANSASTESTER F. L. ENSMINGERAPPROVED A. H. JacksonDRILL STEM TEST NO. 1 SUCCESSFUL NO. MIS-RUN NO. MISSSIZE HOLE 7 7/8 TOOL JT. 4 1/2 FH.RUBBER SIZE 6 3/4 TEST TOOL SIZE 4 1/2PACKER SET AT 4490 ANCHOR SIZE 4 1/2TOTAL DEPTH WELL 4496 LENGTH ANCHOR 6"PRESSURE RECORDER CAP. 3500 + 3500 DRILL PIPE RUN: DRY ✓ WITH FLUID

RESULTS:

PACKER SET 7:45 A.M. TOOL OPEN 7:50 P.M. TOOL OPEN 1 HRS.BLOW Very sweet for 28 MIN, Blow intermittent Husky
Tool.RECOVERY 30 ft drilling mud.SHUT IN PRESSURE TIME 20 MIN. MUD WT. 9.7 VIS. 52 WATER LOSS 8.8"BHP 0 IFP 0 FFP 0 HYDROSTATIC HEAD 2500EXTRA EQUIPMENT Jars + Safety Sub. JARS Brown NO. 1416 SIZE 3 1/2OPERATOR TIME 10 TOOL RENTAL TIME 6

BEE FORMATION TESTING CO.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.



BEE FORMATION TESTING CO.

TEST TICKET

DATE 1-4-56

P. O. BOX 491

GREAT BEND, KANSAS

3ch
Nº

1341

CUSTOMER'S
ORDER NO.

NAME OF COMPANY

C. R. A.

ADDRESS TO MAIL INVOICE

Box 765 Great Bend Kans.

ADDRESS TO MAIL PRESSURE CHARTS

Same

LEASE

Harkness

WELL NO.

C-4

COUNTY

Ness

STATE

KANS

TESTER

F. L. ENSMINGER

APPROVED

P. H. JACKSON

DRILL STEM TEST NO.

2

SUCCESSFUL NO.

MIS-RUN NO.

MISS

SIZE HOLE

7 7/8

TOOL JT.

4 1/2 P.H.

RUBBER SIZE

6 3/4

TEST TOOL SIZE

4 5/8

PACKER SET AT

4491

ANCHOR SIZE

4 1/2

TOTAL DEPTH WELL

4501

LENGTH ANCHOR

10"

PRESSURE RECORDER CAP.

3500 + 3500

DRILL PIPE RUN: DRY

✓

WITH FLUID

RESULTS:

PACKER SET

5125

M. TOOL OPEN

5128

M. TOOL OPEN

1

HRS.

BLOW

Wash for 37 MIN. Did.

RECOVERY

25 ft drilling mud.

SHUT IN PRESSURE TIME

20 MIN

MUD WT.

9.7

VIS.

52

WATER LOSS

8.8 cc

BHP

350

IFP

0

FFP

50

HYDROSTATIC HEAD

2500

EXTRA EQUIPMENT

Grad + Safety Sub

JARS

Bowen

NO.

1416

SIZE

3 1/2

OPERATOR TIME



10

TOOL RENTAL TIME

6

BEE FORMATION TESTING CO.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.



TEST TICKET

BEE FORMATION TESTING CO.

P. O. BOX 491

GREAT BEND, KANSAS

No 1342

DATE 1-5-56CUSTOMER'S
ORDER NO.NAME OF COMPANY C. R. A.ADDRESS TO MAIL INVOICE 765 Great Bend Kans.ADDRESS TO MAIL PRESSURE CHARTS SAMELEASE Warkness WELL NO. C-4 COUNTY Ness STATE KANSTESTER F. H. ENSMINGER - APPROVED P. A. Jackson
DRILL STEM TEST NO. 3 SUCCESSFUL NO. 3 MIS-RUN NO. MISSSIZE HOLE 7 7/8 TOOL JT. 4 1/2 FH
RUBBER SIZE 6 3/4 TEST TOOL SIZE 4 7/8
PACKER SET AT 4497 + 4505 ANCHOR SIZE 4 1/2
TOTAL DEPTH WELL 4565 LENGTH ANCHOR 8 ft + 58 ft tail pipe
PRESSURE RECORDER CAP. 3500 + 3500 DRILL PIPE RUN: DRY ✓ WITH FLUID

RESULTS:

PACKER SET 6:10 P.M. TOOL OPEN 6:14 P.M. TOOL OPEN 1 HRS.BLOW Wash for 25 min. 2nd.Straddle Packer.RECOVERY 60 ft heavy oil cut mud.SHUT IN PRESSURE TIME 20 min. MUD WT. 9.7 VIS. 52 WATER LOSS 8.8 in
BHP 800 IFP 0 FFP 100 HYDROSTATIC HEAD 2550
EXTRA EQUIPMENT Iron + Safety Sub. JARS Bowen NO. 1416 SIZE 3 1/2
OPERATOR TIME 12 TOOL RENTAL TIME 6
straddle job

BEE FORMATION TESTING CO.

SHALL NOT BE LIABLE FOR DAMAGE OF ANY KIND TO THE PROPERTY OR PERSONNEL OF THE PARTY FOR WHOM A TEST IS MADE, OR FROM ANY LOSS SUFFERED OR SUSTAINED, DIRECTLY OR INDIRECTLY, THROUGH OR IN THE COURSE OF THE USE OF ITS EQUIPMENT, ALL OF WHICH LOSS OR DAMAGE IS ASSUMED BY THE CUSTOMER. TOOLS LOST OR DAMAGED IN THE HOLE SHALL BE PAID FOR AT THE COST OF THE PARTY FOR WHOM TEST IS MADE.

