


Section 21 Township 19 Range 10-W

Well No. #1 Linke

Company Armer Drlg
Silica Pool



Sec. 21 Twp. 19 R. 10W ✓

Well No. #1 Linke Farm

Armer Drlg. Company

Contractor

Silica Pool


990' Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330' Ft. from W. Line

SW NW NE



1950 Elev. 1764' REPORT

3/8 Spud 2-28-50
8-5/8" @ 165'
Drlg. 2070'
3/22 8 5/8" @ 165'
Heebner 2832'
Br Lime 2941'
Lans 2966'
DST 3030-36
Rec wtr
DST 3148-58
Rec mud
BKC 3248
Arb. 3292'
TD 3316'
D&A
Aband.

ABANDONED

Kansas

Map No. _____ Sec. 21 Twp. 19 R. 10W

Well No. 1 Linke

Armer Drlg. _____ Company

_____ Contractor

SW NW NE

El. 1764

SECTION FLAT

990 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line



Rice County

Location _____

Rig up _____

Drilling and Remarks:

Spud 2-28-50

8 5/8" @ 165

drlg. 2070

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

J. E. TYRA

MAR 8 1950 19

Scout

MEMORANDUM

APR 10 1950

- Scout Cards
- Land Small Map
- Land Wall Map
- Tracings
- France Map
- Pierce Map
- Misc.

[Handwritten signature]

[Handwritten mark]

Map No. _____ Sec. 21 Twp. 19 R. LOWWell No. 1 Linke

Armer Drlg.

Company _____

Contractor _____

SW NW NE


E1. 1764

SECTION PLAT

990 Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 Ft. from W. Line

Rice County

Location _____

Rig up _____

Drilling and Remarks:

8 7/8" @ 165
 Heebner 2832
 Br. line 2941
 Kans. 2966
 DST. 3 @ 30-36
 Rec. water
 DST 3148-58
 Rec. mud
 BKC. 3248

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

MAR 22 1950 19

J. E. TYRA

Scout

