

DX 78-1

KANSAS

Section 35 Township 20 Range 6W

Well No. #1 Harder "A"

Company Sterling Drlg. & Davis-Childs.

NORTH

0							

SOUTH

WEST

EAST

Rice

SEC.	TWP.	R. KANSAS
35	20	6 W

WELL NO.

14 Harder "A" FARM

COMPANY

Sterling Drlg. & Davis-Childs

CONTRACTOR

Sterling

Welch-Bornholdt Pool

990 _____ Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

330 _____ Ft. from W. Line

SW NW NW

WEST

NORTH							
0							
SOUTH							

EAST

	ELEVATION	REPORT
1955	1605'	
1/19 3/16	Location Spud 1-22-55, Oil Well TD 3434 8" @ 120 , Lans 2830, Miss 3386 TD 3396, 5" @ 3396, DD 3434 PB 3422 frac Comp: 2 5 BOPD	
	COMPLETED	

County Rice State Kansas
 Sec. 35 (Blk.) 20 (Sur.) 6W Map No.
 Operator Sterling Drlg. & Davis-Childs
 Well No. 4 Farm Harder
 Elev. _____ Location SW NW NW

0							

990 Ft. From N Line NW

330 Ft. From W Line Quarter

1st. Report JAN 1 9 1955

Completion _____

Remarks _____

Sterling - Contr.

Spudding Date _____

Drlg. Data Welch-Bornholdt Pool

Location

FABEN GILSTRAP

County Rice State Kansas
 Sec. 35 (Blk. 20 (Sur. 6W Map No.
 (Twp.) (Rge.)
 Operator Sterling Drlg. & Davis-Childs
 Well No. 4 Farm Harder "A"
 Elev. 1605 Location SW NW NW

0							

990 Ft. From N Line NW
330 Ft. From W Line Quarter

1st. Report

Completion MAR - 1 6 1955

Remarks Welch-Bornholdt Pool
Sterling - Contr.

Spudding Date 1-22-55

Drlg. Data Oil well TD 3434

8" @ 120 Lans. 2830 Miss. 3386

TD 3396 5" @ 3396 DD 3434 PB 3422

frac Comp. 25 bopd

FABEN GILSTRAP