

Stafford


KANSAS

SECTION 28 TOWNSHIP 21 RANGE 14W

WELL NO. #1 Ratzläff

COMPANY Hilton Drlg.

NORTH W/2 SW SW



SOUTH

County Stafford Elev. \_\_\_\_\_  
 Sec. 28 Twp. 21 Rgs. 14W  
 Company Hilton Drlg.  
 Farm Name Ratzlaff No. 1

TOPS	DEPTH	LOG	DATUM
Anh.			
Tp.			
H.			
Tr.			
Dg.			
Bl.			
L.			
K.C.			
B.K.C.			
Ce.			
C.			
M.			
M.			
K.			
Mz.			
Mo.			
V.			
S.			
S.			
A.			
R.			
Pe.			
G.			
TD.			

Loc. in Sec. W/2 SW SW

Geol. \_\_\_\_\_

Contr. \_\_\_\_\_

~~Co. Tools~~

Pool LANCOGIV

Radium Townsite

FEB 13 1957	
FIRST	REPORT
o	

Date Comm. 2-7-57  
8" @ 278/225 SD for repairs @ 2297

13

Co.  
No.  
Sec.  
T.  
R.

Co.

County Stafford Elev. 1943  
 Sec. 28 Twp. 21 Rgs. 14W  
 Company Hilton Drlg.  
 FarmName Ratzlaff No. 1

TOPS	DEPTH	LOG	DATUM	Loc. in Sec.
Anh.				W/2 SW SW
TP.				
H.	3300			
Tr.				
Dg.				
Bl.	3416			
L.	3426			
K.C.				Geol.
B.K.C.				Cont.
Ce.				Co. Tools
C.				Pool <u>LINCOLN</u>
M.				Radium Townsite
M.				
K.				
Mz.				
Mo.				
V.	3703			<div style="border: 1px solid black; padding: 5px; text-align: center;"> <p><b>ABANDONED</b></p> <p>FEB 27 '57</p> </div>
S.	3741			
S.				
A.	3799			
R.				
PE.				
G.				
TD.	2816			

Sec.

No.

Sec.

T.

R.

Date Comm. 2-7-57

8" @ 278/225 SD for repairs @ 2297

FEL 4 5: DST 3567-84 30" sec 26'  
 Md FP 0 BHP 790/20" DST  
 3610-26 or 30" 10' Md FP 0  
 BHP 60/20" DST 3706-23 or  
 30" 5' Md FP 0 BHP 0/20"  
 ID 3751 7'58" DST 3740-82 3  
 line 270' Mdy oil FP 0-125  
 BHP 615/30" DST 3804-16

1hr 2640' SW FP 700-1230  
1240/20''

D E A