

KANSAS


Stafford

Section 4 Township 21 Range 12WWell No. 2 Secail *(Special)*Company Yarnell & Parrish ?

Workman

NORTH

WEST



EAST

SOUTH

KANSAS

Stafford

Sec. 4 Twp. 21 R. 12W

Well No. #2 Secail Farm

Yarnell & Parrish Company


Workman Pool

990' Ft. from N. Line

 Ft. from S. Line

990' Ft. from E. Line

 Ft. from W. Line



SW NE NE

1949

Elev. 1854' REPORT

6/29

Location

7/6

8" @ 275'

Lansing 3186'

Arb. 3412'?

TD 3412'

5" @ 3409'

7/12

Simpson 3411'

Sands 3413'

Arbuckle 3416' corrected

TD 3420'

5" @ 3417'

1800' oil 1 hr

7/20

"

7/27

Arb 3416'

5" @ 3417'

Pump 423 oil Pot.

Gr. 40°

TD 3420'

COMPLETED

Kansas

Workman Pool

Map No. _____ Sec. 4 Twp. 21 R. 12WWell No. 2 SecailYarnell & Parrish Company

Contractor

SW NE NE

FIRST REPORT
SECTION PLAT990 Ft. from N. Line Ft. from S. Line990 Ft. from E. Line Ft. from W. Line

			o

Stafford CountyLocation X

Rig up _____

Drilling and Remarks:

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth _____

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JUN 29 1949

19

S. J. LEWIS Scout

Kansas

Workman Pool

Map No. K 46 Sec. 4 Twp. 21 R. 12WWell No. 2 Secail

Yarnell & Parrish

Company

COMPLETE

Contractor

SW NE NE

E 1834
SECTION PLAT

990

Ft. from N. Line

Ft. from S. Line

990

Ft. from E. Line

Ft. from W. Line

			0

Stafford County

Location

Rig up

Drilling and Remarks:

Ce X34165" C3417Pray 422 oil Prod.40-2 in.

RECORD

Cased _____ in., _____ ft.

Sand _____

Gas _____

Oil _____

Total Depth 3420

PRODUCTION

1st 24 hrs. Nat. _____

1st 24 hrs. after shot _____

Gas _____ Cu. Ft.

Dry Hole _____

Abandoned _____

Date

JUL 27 1949

S. J. LEWIS

Scout