

Map No. *Kingman* **KANSAS** Sec. *16* Twp. *27* R. *7W*
 Well No. *36* *1 Rayl*

Prof. A. Eeger Company
 Contractor

SECTION PLAT

0			

..... Ft. from N. Line
320 Ft. from S. Line
 Ft. from E. Line
320 Ft. from W. Line

FIRST REPORTS

Twin dry hole

Location.....

Rig up.....

Drilling and Remarks:

Gas Test
July 11 25

RECORD

Cased.....in.,ft.
 Sand.....
 Gas.....
 Oil.....
 Total Depth.....

PRODUCTION

1st 24 hrs. Nat.....
 1st 24 hrs. after shot.....
 Gas.....Cu. Ft.
 Dry Hole.....
 Abandoned.....

Date

JUL 17 1929

S. J. LEWIS Scout

Moody

Moody

Returned.....	<i>OK</i>
Cards.....	<i>OK</i>
Tracing.....	<i>OK</i>
France Map.....	<i>OK</i>
Scarborough Map.....	<i>X</i>
Moody Map.....	
Scarborough Plat Book.....	
Moody Plat Book.....	

Map No. *Kingman* **KANSAS** Sec. *16* Twp. *27* R. *7W*

Well No. *36* *1 Rayl.*

Pe & Flee ger Company

Contractor

SECTION PLAT

..... Ft. from N. Line

330 Ft. from S. Line

5 Ft. from E. Line

330 Ft. from W. Line

ABANDONED

Location.....

Rig up.....

Drilling and Remarks:

Show gas.
1315-25

RECORD

Cased..... in., ft.

Sand.....

Gas.....

Oil.....

Total Depth..... *1337*

PRODUCTION

1st 24 hrs. Nat.....

1st 24 hrs. after shot.....

Gas..... Cu. Ft.

Dry Hole.....

Abandoned.....

Date

JUL 24 1929

192.....

S. J. LEWIS Scout

W. W. Wood
S. S. S. S.

Returned	
Cards	LB
Tracing	CS
France Map	X
Scarborough Map	X
Moody Map	
Scarborough Plat Book	
Moody Plat Book	