


# KANSAS Stanton

FORM 51 IOM 12-46 PETROL

Section 23 Township 27 Range 39W

Well No. 1 Mater "C"

Company Stanolind





Sec. b 23 Twp. 27 R. 39W

Well No. #1 Mater "C" Farm \_\_\_\_\_

Stanolind Company


Hugoton

\_\_\_\_\_ Ft. from N. Line

50 Ft. from S. Line

\_\_\_\_\_ Ft. from E. Line

50 Ft. from W. Line



SW NE

1947 REPORT  
Elev. 3106'

4/2 10" @ 671'  
WOC

4/9 Drlg. 2440'.

4/15 TD 2519'  
7" @ 2289'  
RUST

4/23 " "

4/29 " "

5/7 " "

5/13 " "

5/20 " "

5/27 " "

6/3 TD 2522  
100 acid

6/10 " "

6/17 " "

OVER

6/24 TD 2522'  
1000 Acid.

7/1 " "

7/9 7" @ 2289'  
3000 Acid  
4,263,000 Gas  
402<sup>#</sup> R. Pr.  
TD 2522'

**COMPLETED**

Map No. \_\_\_\_\_ Sec. 23 Twp. 27 R. 39W

Well No. 1 Mater "C"

Stanolind Company

**FIRST REPORT** Contractor \_\_\_\_\_

SW NE

SECTION PLAT


\_\_\_\_\_ Ft. from N. Line

50 Ft. from S. Line

\_\_\_\_\_ Ft. from E. Line

50 Ft. from W. Line

Stanton County

Location \_\_\_\_\_

Rig up \_\_\_\_\_

Drilling and Remarks:

10" @ 671 WOC

RECORD

Cased \_\_\_\_\_ in., \_\_\_\_\_ ft.

Sand \_\_\_\_\_

Gas \_\_\_\_\_

Oil \_\_\_\_\_

Total Depth \_\_\_\_\_

PRODUCTION

1st 24 hrs. Nat. \_\_\_\_\_

1st 24 hrs. after shot \_\_\_\_\_

Gas \_\_\_\_\_ Cu. Ft.

Dry Hole \_\_\_\_\_

Abandoned \_\_\_\_\_

Date

APR 2 1947 19

S. J. LEWIS Scout

Misc. Small Maps E  
Cards RPB  
Tracing ✓  
France Map ✓  
Scarborough Map ✓  
Pierce Map ✓  
Geological Dept. \_\_\_\_\_  
Pierce Plat Book \_\_\_\_\_

Map No. \_\_\_\_\_ Sec. 23 Twp. 27 R. 39W

Well No. 1 Mater "C"

Stanolind Company

COMPLETE

Contractor

SWNE

*E. J. 106*  
SECTION PLAT

\_\_\_\_\_ Ft. from N. Line

50 Ft. from S. Line

\_\_\_\_\_ Ft. from E. Line

50 Ft. from W. Line


Stanton County

Location \_\_\_\_\_

Rig up \_\_\_\_\_

Drilling and Remarks:

*7' @ 2259  
30000 acid  
4,963,000 Gas*

*402 \* R. 12*

RECORD

Cased \_\_\_\_\_ in., \_\_\_\_\_ ft.

Sand \_\_\_\_\_

Gas \_\_\_\_\_

Oil \_\_\_\_\_

Total Depth 2522

PRODUCTION

1st 24 hrs. Nat. \_\_\_\_\_

1st 24 hrs. after shot \_\_\_\_\_

Gas \_\_\_\_\_ Cu. Ft.

Dry Hole \_\_\_\_\_

Abandoned \_\_\_\_\_

Date

JUL 9 1947 19 \_\_\_\_\_

S. J. LEWIS Scout

Misc. Small Maps C  
Cards RIB.  
Tracing ✓  
France Map ✓  
Scarborough Map X  
Tierce Map ✓  
Geological Dept. \_\_\_\_\_  
Folio Flat Book \_\_\_\_\_