


Section 19 Township 30 Range 11W

Well No. 1 Wulf

Company O. H. Parker



SEC.	TWP.	R.
19	30	11W

WELL NO. **1 Wulf** FARM

COMPANY **O. H. Parker**

CONTRACTOR


Wildcat

_____ Ft. from N. Line

_____ Ft. from S. Line

_____ Ft. from E. Line

_____ Ft. from W. Line



SW SW SE

1/2 mi S D-X

1955	ELEVATION 1826	REPORT
------	-------------------	--------

- 6/29 Location
- 7/7 "
- 7/14 Location
- 7/22 Location
- 7/28 Location
- 8/3 Abd. Location

ABANDONED

County Barber Elev. _____
 Sec. 19 Twp. 30 Rge. 11W
 Company O. H. Parker
 Farm Name Wulf No. 1

Co.

TOPS	DEPTH	LOG	DATUM
Anh.			
Tp.			
H.			
Tr.			
Dg.			
B.L.			
L.			
K.C.			
B.K.C.			
Ce.			
C.			
M.			
M.			
K.			
Mz.			
Mq.			
V.			
S.			
S.			
A			
R.			
Pe.			
G.			
T.D.			

Loc. in Sec. SW SW SE

Geol. _____

Contr. _____

Pool Wildcat

1/2 mile
FIRST REPORT
 JUN 29 '55
 0

Lse.

No.

Sec.

T.

R.

Date Comm. _____
 Location _____

26

JUL 1 1955

Scout Cards	mm
Land Small Map	_____
Land Wall Map	_____
Tracings	_____
France Map	_____
Pierce Map	_____
Misc.	_____

County Barber Elev. 1826 Co. _____
 Sec. 19 Twp. 30 Rge. 11W
 Company O. H. Parker
 FarmName Wulf No. 1

TOPS	DEPTH	LOG	DATUM
Anh.			
TP.			
H.			
Tr.			
Dg.			
Bl.			
L.			
K.C.			
B.K.C.			
Ce.			
C.			
M.			
M.			
K.			
Mz.			
Mq.			
V.			
S.			
S.			
A			
R.			
PE.			
G.			
T.B.			

Loc. in Sec. SW SW SE

Geol. _____

Cont. _____

Pool Wildcat

ABANDONED

Date Comm. AUG 3 1935 No. _____
 Abd. location _____ Sec. _____

26

T. _____
 R. _____

AUG 10 1955

Scout Cards *JC*
Land Small Map
Land Wall (.....)
Tracings
France Map
Pierre Map
Misc.