PANHANDLE EASTERN PIPE LINE COMPANY

Murphy 1-15 C of SW/4 Section 15-32S-41W Morton County, Kansas

Formation Tops

Marmaton	4288 ¹
Cherokee	4414
Atokan	4553 †
Morrowan Shale	4808 1
Lower Morrowan Ss.	5122'
Lower Morrowan Ss.	5196'
Lower Morrowan Ss.	5229'
Mississippian	5319 '
Total Depth	5482 '

Completion Information

Spud September 16, 1955. Set 289' of 16" casing with 500 sacks cement. Set 1580' of 9 5/8" casing with 800 sacks cement. Set 5400' of 5½" casing with 850 sacks cement. Cleaned out to 5280'. Perforated 24 holes 5204-5210'. Perforated 28 holes 5197-5204'. Acidized with 500 gallons mud acid. Fractured with 10,000 gallons diesel and 20,000# sand. Gauged 2572 MCF.

Completion Test: December 15, 1955.

Gauged (est) 2068 MCF from the

Lower Morrowan Sandstone

5197-5210.

Dually completed with Hugoton Reservoir.