


Section 22 Township 32 Range 6WWell No. #1 RobinsonCompany Adair et al

NORTH



SOUTH

Harper

KANSAS

SEC.	TWP.	R.
22	32	6 W

WELL NO.

1 Robinson

FARM

COMPANY

Adair et al

CONTRACTOR

Adair

Wildcat


Ft. from N. Line

330 Ft. from S. Line

Ft. from E. Line

330 Ft. from W. Line

SW SW NW



	ELEVATION	REPORT
1954	1381'	

8/18 Spud 8-16-54
Drlg.

9/8 Spud 8-16-54 - D&A

TD 4798'

8-5/8" @ 171'

Top 2747', Elgin 2984', Oread 3146',

Heeb 3162', Doug 3283', Stal 3488',

KC 3746', B KC 3988', Miss 4360',

Kh. 4643', Viola 4765', Simp 4786'

DST 4767-87', opn 1 hr., rec. 180'

gc muddy sw, 1080' sli gassy sw,
1680#

TD 4798'

D&A

ABANDONED

County **Harper** State **Kansas**

Sec. **22** (Blk. **32** (Sur. **SW** Map No.

Operator **Adair et al.**

Well No. **1** Farm **Robinson**

Elev.	Location	SW	SW	NE
-------	----------	----	----	----

0

FIRST REPORT

330 Ft. From S Line NW

330 Ft. From ~~W~~ Line Quarter

1st. Report

Completion

Remarks


Adair - Contr.

Spudding Date **8-16-54**

Drig. Data **Wildcat**

drlg.

FABEN GILSTRAP

County Harper State KansasSec. 22 (Blk. Twp.) 32 (Sur. Rge.) 6W Map No.Operator Adair et al.Well No. 1 Farm RobinsonElev. 1381 Location SW SW NW330 Ft. From S Line NW330 Ft. From W Line Quarter

1st. Report

Completion SEP 8 1954Remarks WildcatAdair - Contr.Spudding Date 8-16-54Drig. Data D & A TD 47988 5/8" @ 171 Top. 2747 Elgin 2984Oread 3146 Heeb. 3162 Doug. 3283Stal. 3488 KC 3746 B KC 3988Miss. 4360 Kh. 4643 Viola 4765Simp. 4776 DST 4767-87 open 1 hr.Rec. 180' gc muddy sw 1080' sli. gassysw 1680# TD 4798D & A

FABEN GILSTRAP