


Section 17 Township 34S Range 43WWell No. #o-2 Interstate "B"Company P. E. P. L.

Morton

SEC.

17

TWP.

34

KANSAS

R.

43W

WELL NO.

B-0-2

#0-2 Interstate "B"

FARM

COMPANY

P.E.P.L

CONTRACTOR

Interstate


_____ FT. FROM N. LINE

_____ FT. FROM S. LINE

_____ FT. FROM E. LINE

_____ FT. FROM W. LINE

C SW SW



1956

ELEVATION

REPORT

8-8

Comm. 7-31-56

10" @ 140 w/250

7" @ 1137 w/450

Drlg. 2555

County Morton

Elev.

Sec. 17Twp. 34SRge. 43WCompany P. E. P. L.Farm Name Interstate "B"No. 0-2

TOPS

DEPTH

LOG

DATUM

Loc. in Sec.

Anh.

Tp.

H.

Tr.

Dg.

Bl.

L.

K.C.

B.K.C.

Ce.

C.

M.

M.

K.

Mz.

Me.

V.

S.

S.

A.

R.

Pe.

G.

T.D.

Gen. SW SW

Geol.

Contr.

Pool

Interstate

FIRST REPORT

Date Comm. 7-31-56

AUG 8 '56

10" 140 w/250; 7" 1137 w/450; D 2555

8221 5 1 300

R. G.

Co.

County Morton Elev. 3535
 Sec. 17 Twp. 34S Rgs. 43W
 Company P. E. P. L.
 Farm Name Interstate "B" No. B-0-2

TOPS	DEPTH	LOG	DATUM	Loc. in Sec.
Anh. <u>W26</u>		<u>2518</u>		Gen. SW SW
Tr.		<u>2718</u>		
H.				
Tr.				
Dg.				
Bl.				
L. <u>C80</u>		<u>2958</u>		Geol.
K.C. <u>639</u>		<u>3146</u>		
B.K. <u>Marm</u>		<u>3236</u>		Contr.
Ce.		<u>3234</u>		
C. <u>Mish</u>		<u>4148</u>		
M. <u>Purdy</u>		<u>4224</u>		Pool Interstate
M.				
K.				
Mz.				
Me.				
V.				
S.				
S.				
A.				
R.				
Pe.				
G.				
TD	<u>4310</u>			

COMPLETE

OCT 17 '56

Lse.

No.

Sec.

T.

R.

Date Comm. 7-31-5610" 140 w/250; 7" 1137 w/450; D 2555

NOV 15 '56 4112 AUG 22 '56 DST 4220
-45 lhr 2 1/2" ga 870 MCF
died rec 100' oil + 100' SW
170-800 # 1160/20" 4 1/2 E
4304/400 CO 4269 20/4225
-30 t-st 19 Boph + 2 Boph
AUG 29 '56 SEP 5 '56 SEP 12 '56 SEP 19 '56 SEP 26 '56
OCT 3 '56 OCT 10 '56 OCT 17 '56 Ph. P. 118
Board 40% into 9200 39°