

DX 78-1


Morton

KANSAS

Section 29 Township 34 Range 43 W

Well No. # 3 U.S.A. "D"

Company Huber Corp



Morton		KANSAS
SEC.	TWP.	R.
29	34	43W
WELL NO.		
#3 U.S. A. "D"		FARM
COMPANY		

Huber Corp.

CONTRACTOR

Co. Tools.


Interstate Pool NORTH

660 Ft. from N. Line

Ft. from S. Line

Ft. from E. Line

660 Ft. from W. Line



C NW SE

	ELEVATION	REPORT
1955	3508'	

1/5
2/9


Location

Spud 1-7-55 Oil well TD 4251
 8" @ 1200 Top 2706 Lans 2940
 Morrow 4074 Purdy sd 4166 B. Purdy
 4206 TD 4250 DD 4251 5" @ 4249
 CO to 4219 8/4202-04 5-6 BSWPH
 8/4192-94 FU 1500' oil S/3 to 4
 BOPH 4 hr. 56/4178-92 SI 1 1/2 hrs.
 48/4166-78 F/38.38 BO 1 hr.
 F/20 BO Comp. F/669 BOPD 4% wtr.

COMPLETED

FABEN GILSTRAP

County Morton State Kansas
 Sec. 29 (Blk. 34) (Sur. 43W) (Rge. Map No.)
 Operator Huber Corp.
 Well No. 3 Farm U.S.A. "D"
 Elev. 3508 Location C NW SE



660 Ft. From N Line SE
660 Ft. From W Line Quarter
 Ist. Report
 Completion FEB 9 1955
 Remarks Interstate Pool
Co. tools
 Spudding Date 1-7-55

*Drig. Data Oil well TD 4251
8" @ 1200 Top. 2706 Lans. 2940
Morrow 4074 Purdy sd. 4166 B. Purdy 4206
TD 4250 DD 4251 5" @ 4249 CO to 4219
8/ 4202-04 5 to 6 bswph 8/ 4192-94
FU 1500' oil S/ 3 to 4 bophr 4 hr.
56/ 4178-92 ST 1 $\frac{1}{2}$ hr. 48/ 4166-78
F/ 38.38 bo 1 hr. F/ 20 bo
Comp. F/ 669 bopd 4% wtr.

FABEN GILSTRAP