
Field Interstate

State Kansas

County Morton

Company Huber Corp.

Farm U.S.A. "D"

Well No. 4

Sec. 29 Twp 34S Blk 43W

Range 43W

fr N

fr E

fr S

fr W

of C NE SE

Contractor Co. tool OFFSET

Remarks

Comm. 1-28-55 Comp. 3-23-55

Elev. 3523 DF T. D. 4272 (log 78) P. B.

Pay 4196-4205 39.50 vty

T. R. 130 BOPD

R. P.

Casing Record: 13 3/4 7

20 10 3/4 5 1/2 4274/200

16 8 5/8 1200/750

1-12-55 LOC

Tops

Sam Top

JAN 19 1955

~~RTD 2707~~

Mon sh 4085

~~3902~~

Mon sd 4188-4200

Scpl.

FEB 2 1955

2750

Log 2734

~~3369~~ 3610'

Log 2964

9 Feb.

~~RTD 35~~

Mon sh 4095

4272

Mon sd 4198

FEB 16 1955

RTD 4272 Log to 4278

5 1/2 4274/200

RUCT Co to 4239?

P&AC log to 4239

8/4226-28

thg w/ phs C 4210

hole filled up with wtr 1500' from surface

Swat sw w/ some oil; could not lower wtr. ball.

ret @ 4223 & log runs 4226-284

Coto?

p 8 / 4218-20

ran by w/pk

hole filled with SW to 1500' from surface; could not work down.

ref C 4212 by pump 4218-20 w/p 5 say

Coto?

p 36 / 4196-4205

ran by to 4208

swell on east 760 + 500 of water in 10 hrs.

M.O.R.T.

FEB 23 1955

waiting in pump unit

2 mar.

POP & WOT

MAR 9 1955

MAR 16 1955

~~State test~~ State physical potential

130 bopd plus $4\frac{1}{2}\%$ SW

~~Held for top~~

MAR 23 1955

~~State physical potential~~
39.5° C only

⌄