

Hansen #1 Hansen (fee)

Phillips
21-5-200
CSE SE
(150' SE)
El 2169

an 1675 +494

maxmullen (C50)

T 3076 -907

3395-3400 ^{over-bur. por} + stain

LKC 3273-1104

3479-80 good por & sat

BKC 3521 -1352

3497-3500 fair por & sat

top Penn Syd ls 3553-1384

3554-12 ^{fair por} ^{to good sat} ^{extension}

^{over} 3585 (1416) + 3569 ^{or} 1400

3553-57 good por & sat

corel 3571 no show

corel 3575 " "

corel 3579 " "

front end log

McKee

En 1675 (+494)

Howrd 3068

T 3130 (-961)

Hebby 3280

LKC (front ls) 3307/1136

KC? 3320 (-1154)

WST 3427

BKC 3519 (-1350)

Penn Syd SE 3522

En A 3569 -1400

A (fresh 3585 -1416

corel 3571 no sho 3569-85 dol & sh

no show

(12/4) corel 3575 no sho

(13/4 h) corel 3579 no sho

corel 3583 good odor - ^{mostly sh} ^{por all the way} no stain

Core 3583-88 (see 412 p)

2' of gneiss with dol nodules

2 1/2' sandy dol on well sat - fair por

sat 5 1/2 3585 1/2 Rust 3588

(over)

did not work sample

8/12 dull plug 900' at rate
drill 3594 HB no ma got 3300
1500' at 20 hr
later at 3585 - 1416 (good del some sd 3569 -1400)
(fuel)

perf 3551-59 27 shot no increase
Swit 2.6 @ 1.0 PH acid did not help

got 153 @