

Section 12 Township 9 Range 22WWell No. 2 ThyfaultCompany M. B. Armer

NORTH

14

							0

SOUTH

WEST

EAST

Graham

KANSAS

SEC.	TWP.	R.
12	9	22W ✓

WELL NO.

#2 Thyfault

FARM

COMPANY

M.B. Armer

CONTRACTOR

Armer

W. Morel Pool

NORTH

Ft. from N. Line

330 Ft. from S. Line

330 Ft. from E. Line

Ft. from W. Line

							0

WEST

EAST

SOUTH

SE SE SE

	ELEVATION	REPORT
1954	2280'	


1/20 M I R

1/27 8" @ 156
Drlg. 2795'

2/3 Spud 1-18-54 D & A TD 3843
 8" @ 156 Heeb 3463 Tor 3487
 Lans. 3503 B KC 3707
 DST 3565-3602 open 1 hr rec 145' wtr.
 & SSO 0# Arb. 3823'
 TD 3843' D & A

ABANDONED

County Graham State Kansas
 Sec. 12 (Blk. 9) (Sur. 22W) (Twp.) (Rge.) Map No.
 Operator M. B. Armer
 Well No. 2 Farm Thyfault
 Elev. 2280 Location SE SE SE



330 Ft. From S Line SE
330 Ft. From E Line Quarter
 1st. Report
 Completion FEB 3 1954
 Remarks W. Morel Pool
Armer - Contr.
 Spudding Date 1-18-54

Drlg. Data D & A TD 3843
8" @ 156 Heeb. 3463 Tor. 3487
Lans. 3503 B KC 3707 DST 3565-3602
open 1 hr. Rec. 145' wtr. & SSO 0#
Arb. 3823 TD 3843

D & A

J. G. McGEHEE