

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72
FORM CP-1
RECEIVED
STATE CORPORATION COMMISSION
AUG 26 1974
CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING APPLICATION FORM
File One Copy

15-147-20042-00-00

Lease Owner Leland R. Baird

Address Logan, Kansas

Lease (Farm Name) Kent "G" Well No. 2

Well Location NE NW NE Sec. 22 Twp. 15 Rge. 18W ~~(E)~~ ~~(W)~~

County Phillips Total Depth 3552 Field Name Huffsutter

Oil Well Gas Well Input Well SWD Well Rotary D & A

Well Log filed with application as required Yes

Date and hour plugging is desired to begin To begin Pulling casing last of August or first of Sept, 1974

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:
Albert Unruh Address 1909 Polk, Great Bend, Ks

Plugging Contractor Southwest Casing Pulling Co License No. _____

Address P.O. Box 522 Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to:

Name Leland R. Baird

Address Logan, Kansas

and payment will be guaranteed by applicant or acting agent.

Signed: [Signature]
Applicant or Acting Agent

Date: _____

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian
WICHITA, KANSAS 67217

August 26, 1974

15-147-20042-00-00

WELL PLUGGING AUTHORITY

Well No.	2
Lease	Kent "G"
Description	NE NW NE 22-1-18W
County	Phillips
Total Depth	3552'
Plugging Contractor	Southwest Casing Pulling


Leland R. Baird
Logan, Kansas 67646

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. Leo Massey, P. O. Box 582, Hays, Kansas 67601
is hereby assigned to supervise the plugging of the above named well.