KANSAS

Form CP-3 Rev. 6-4-68

STATE CORPORATION COMMISSION

RECEIVED STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

OCT 2 3 1973

J, Lewis Brock Administrator P. O. Box 17027 Wichita, Kansas 67217 15-153-20170-00-00

CONSERVATION DIVISION Wichita, Kansas

Well Plugging Supervisor

Lease Name Bucy Sec. 9 Twp. 1 Rge. (E) (W) 3 County Rawlins Total Depth 4150' Abandoned Oil Well Gas Well Input Well SWD Well D & A X Other well as hereafter indicated Plugging Contractor Chief Drilling Company, Incorporated, Address Above License No. Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'-8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Bu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. Cement thru DP from 275' to 200'. Pulled DP, set bridge 4 h0' with ½ sack hulls and	N		•				
County Rawlins Total Depth 4150' Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Chief Drilling Company, Incorporated, Address Above License No. Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. For of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge @ h0' with \(\frac{1}{2} \) sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Operator's Full Name_	Chief Drilling Com	pany, Incorpora	ted & E	ill J.	Porter,	
County Rawlins Total Depth 4150' Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Chief Drilling Company, Incorporated, Address Above License No. Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. For of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge @ h0' with \(\frac{1}{2} \) sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Complete Address	905 Century Plaza,	Wichita, Kansa	IS.	annangen senjanikan mangan		
Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Chief Drilling Company, Incorporated, Address Above Incense No. Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge 40' with 2 sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Lease Name	Bucy	Wel	ll No		sales	
Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated Plugging Contractor Chief Drilling Company, Incorporated, Address Above Incense No. Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge 40' with 2 sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Location	SE-NW	Sec.	Twp.	l Rge.	(E)_	(w)_3.
Plugging Contractor Chief Drilling Company, Incorporated, Address Above License No. Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Bu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge 40' with \frac{1}{2} sack hulls and 10 Cu. Ft. cement to bottom of cellar.	•	,					
Address Above License No. Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge 40' with \(\frac{1}{2} \) sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Abandoned Oil Well	Gas Well	Input Well	SW	D Well_	D	& A_X
Plugging Contractor Chief Drilling Company, Incorporated, Address Above License No. Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge 40' with 2 sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Other well as hereaft	er indicated			TO SEE SHOULD BE SEEN STATE OF THE SECOND SE		
Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge 3 40' with ½ sack hulls and 10 Cu. Ft. cement to bottom of cellar.							ngung si kumumin di Manuning sayar 7452 sac
Operation Completed: Hour 1:30 PM Day 16 Month 10 Year 1973 The above well was plugged as follows: 255'8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge 3 40' with ½ sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Address	Above		Lice	nse No.	c	
The above well was plugged as follows: 255'-8 5/8" Surface casing, cement circulated with 160 Sx. Top of Dakota section 3 1800'. Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge 40' with 2 sack hulls and 10 Cu. Ft. cement to bottom of cellar.							1973
Circulated hole from bottom with heavy mud. Pulled DP to 2025' and displaced 110 Eu. Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge @ 40' with ½ sack hulls and 10 Cu. Ft. cement to bottom of cellar.	255'8 5/8" Surface	casing, cement circ	ulated with 160	Sx.	Sandania myydding farfallau		nijananca alaina di Antonomina (Antonomina
Ft. cement thru DP from 2025' to 1700'. Pulled DP to 275' and displaced 30 Cu. Ft. cement thru DP from 275' to 200'. Pulled DP, set bridge @ 40' with ½ sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Top of Dakota section	@ 1800¹•					
cement thru DP from 275' to 200'. Pulled DP, set bridge @ 40' with ½ sack hulls and 10 Cu. Ft. cement to bottom of cellar.	Circulated hole from 1	oottom with heavy m	ud. Pulled DP	to 2025	and di	isplaced	110 Eu.
10 Cu. Ft. cement to bottom of cellar.	Ft. cement thru DP fro	om 2025' to 1700'.	Pulled DP to 2	75 ' a nd	displa	ced 30 C	u. Ft.
	cement thru DP from 2	75' to 200'. Pulle	d DP, set bridge	e @ 140!	with }	sack hu	lls and
INVOLCED	10 Cu. Ft. cement to	bottom of cellar.					
INVOLCED	tione enthus a creative make make people and institution and along as a free place in influence and a state in individual developed and an institution of the state in individual developed and an ind		engy vill 2-leften singer <mark>dem fransk film for det de leger vill de le 2-lea tribité de 2-l</mark>				
INVOLCED	 conditions on the content of the conte	Aliakahiran keting Pintanin ilan oleh telapun ilan ika ketika dan dia penuntuk ketikan kenali dan dibantak bab	neset kilokule, je zavojen komanik od ovoji do 1700. ili i sakis okorovalno nastine do v manimb († 1704).	A Control of the Cont			ali ilija kan kan kan kan kan kan kan kan kan ka
ுக்கு இது இது இரு இருக்கு இது இருக்கு இது இருக்கு	INVOLCED	uteria, eta languaren energiarra parenia irritaria balendaren erritarren barran da en da en da en da en da en d		anamintanan kankai yi yu aninin ilirin k			Colonia (III) etiennin eritiintimenten urse
	10/23/73	•	hambie	· //.	4	1 to en	urre