CARD MUST BE TYPED

NOTICE OF State of Kansas TO DRILL (see rules on reverse side)


CARD MUST BE SIGNED

Starting	Date:	-10-85		API Numb	er 15- 153-20,600 r00-00		
Starting	Dute	month day	year	1:30	,		
OPERAT	OR: License	6033	• • • • • • • • • • • • • • • • • • • •	SE SE	East Sec3Twp.1s, Rge .34. X West		
Name .Murfin.Dr.l.g					ion)		
Address2.5.0. N Water., Suite 3.0.0					.1.00 Ft North from Southeast Corner of Section		
City/State/Zip Wichita, Ks. 6.7.20.2.					1.0.0 Ft West from Southeast Corner of Section		
Contact Person Todd .Aikins					(Note: Locate well on Section Plat on reverse side)		
Phone 3.1.62.6.73.24.1.					se or unit boundary line25.4.Q feet.		
CONTRACTOR: License #6.0.3.3.					Rawlins23.73		
Name .Murfin DrlgCo					e Cahoj NE B Well# 2-W		
City/State Wichita, KS. 6.7.2.0.2.							
	lled For:	Well Class:	Type Equip		ell within 330 feet :		
□ Oil	□ Swd	X Infield	X Mud Rot	· · · · · · · · · · · · · · · · · · ·	ven within one line:		
☐ Gas	X Ini		Air Rotai		ottom of fresh water120 225 feet		
	O 🔲 Expl	☐ Wildcat	☐ Cable	-	ble water formationunconsolidated		
If OWWO: old well info as follows:					Depth to Bottom of usable water 120. 7.7.5 feet		
Operator					e by Alternate: 1 2 2		
Weli Name					to be set 200 feet		
				Conductor			
Comp Date Old Total Depth				Conductor	pipe if any required		
Projected Formation at TD				get Groung sur	face elevation307.5 feet MSL		
Expected Producing Formations				. I nis Author	rization Expires 10-9-85		
certify that we will comply with K.S.A. 55-101, et seq., plus eventually plugging hole to K.Ç.C. specifications.							
Pate 4-9-85 Signature of Operator or Agent Fide Culture Title Geologist							
ate		. Signature of Operato	n or Agent ⊱∴	odd Aiking	Form 0.4 404		

Must be filed with the K.C.C. five (5) days prior to commencing well

SESURY 'ENLISHM This card void if drilling not started within six (6) months of date received by K.C.C. CONSERVATION DIVISION

NOISAIREGUIAN SECTION OF LAND



Important procedures to follow:

- 1. Notify District office before setting surface casing.
- 2. Set surface casing by circulating cement to the top.
- 3. File completion forms ACO-1 with K.C.C. within 90 days of well completion, following instructions on ACO-1, side 1, and including copies of wireline logs.
- 4. Notify District office 48 hours prior to old well workover or re-entry.
- 5. Prior to plugging, prepare a plugging plan, then obtain agreement from the appropriate district office for an approved plugging plan.
- 6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
- 7. Obtain an approved injection docket number before disposing of salt water.
- 8. Notify K.C.C. within 10 days when injection commences or terminates.
- 9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.

State Corporation Commission of Kansas **Conservation Division** 200 Colorado Derby Building Wichita, Kansas 67202 (316) 263-3238